

**AIRCRAFT ACCIDENT
IDENTIFICATION
NO.**

2 02 27 102

NAVAL AVIATION SAFETY CENTER

GENERAL (Card No. 1)

SUPPLEMENTARY (Card No. 2)

Bureau Number	145396	16-21	Weather		16-21
Reporting Custodian	132	22-24	Kind of Flight	1A1	22-24
Type of Duty	21	25-26	Relative Wind - Direction		25
Major Command	1	27	Relative Wind - Velocity		26
Aircraft Damage	A	28	Relative Wind (Old Code - Not in Use)		27
Aircraft Injury	E	29	Clearance	2	28
Maneuver prior to Accident	M	30	Time of Day	2	29
First Accident type	A1	31-32	Number of other Aircraft	1	30
First Accident phase	431	33-35	Altitude of Occurrence	270	33-35
Second Accident type	58	36-37	POSSIBLE FACTORS	Contributing Cause Factors	36-37
Second Accident phase	A2	38-40		Pilot Factor	38-39
Type of Operation	3	41-42		Other Personnel Factor	41-42
Contributing Cause Factors	1	43-47		Major Material Factor	43
Pilot Factor, First	FG	48-49		Design	44
Pilot Factor, Second	24	50-51		Facilities	45
Pilot Factor, Third	29	52-53	Weather	46	
First other Personnel Factor		54-55	Non-Navy Injury ("R")		47
Second other Personnel Factor		56-57	Number of "A" or "L" or "M" Injury		48-49
Primary Major Material Factor		58	Number of "B" Injury		50-51
Secondary Major Material Factor		59	Number of "C" Injury		52-53
Design		60	Number of "D" Injury		54-55
Facilities		61	Number of "E" Injury	2	56-57
Special Date & Cond.	S U S G J	62-68	Location	A 5 E L C T R	62-68
Type of Flight Hazard		69	Facility Data		69-74
Pri. Cause/Available/Other/Physical/Or-Schedule	1	70	ACCIDENT DAMAGE A ACCIDENT INJURY E FISCAL YEAR 2 SPECIAL ATTN: ("X") X Model Code 17	Don't Count I.D. NO. YR MO DAY TYR SEQ 2 0 2 2 7 1 0 2 11 12 13 14 15 Model	
Causal Fac for Pri-Cause	FG	71-72			
Carrier Hull Number		73-74			
No Personnel Card ("R")		80			

PERSONNEL STATISTICS
(Card No. 3)

File Number	078273	Rank/Rate	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	
Name	(b) (6)	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74		
SS		56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74																										

IBM: PERSONNEL CODED ON REVERSE SIDE ☐

CODED ☒ REVIEWED ☒ LOGGED ☒ PUNCHED ☒ VERIFIED ☒ REVIEWED ☒ REPUNCHED ☒

CODE SHEET REVIEWED BY CLASS DESK ANALYST

(Signature)

(Date)

RECORDS CODE SHEET

SHD 4535 (Rev. 1-62)

NAVAL AVIATION SAFETY CENTER SUPPLEMENTARY (Card No. 21)

Bureau Number	146975	16-21	Weather		16-21
Reporting Command	1	22-24	Kind of Flight	1	22-24
Type of Duty	21	25-26	Relative Wind - Direction		25
Major Command		27	Relative Wind - Velocity		26
Aircraft Damage	A	28	Relative Wind (Old Code - Not in Use)		27
Aircraft Injury	E	29	Clearance	2	28
Maneuver prior to Accident	A	30	Time of Day	2	29
First Accident type	A1	31-32	Number of other Aircraft	1	30
Second Accident phase	431	33-35	Altitude of Occurrence	27	33-35
Second Accident type	58	36-37	Contributing Cause Factors		36-37
Second Accident phase	A2	38-40	Pilot Factor		38-39
Type of Operation	3	41-42	Other Personnel Factor		41-42
Contributing Cause Factors	2	43-47	Major Material Factor		43
Pilot Factor, First		48-49	Design		44
Pilot Factor, Second		50-51	Facilities		45
Pilot Factor, Third		52-53	Weather		46
First other Personnel Factor	H6	54-55	Non-Mary Injury ("R")		47
Second other Personnel Factor		56-57	Number of "A" or "L" or "M" Injury		48-49
Primary Major Material Factor		58	Number of "B" Injury		50-51
Second Major Material Factor		59	Number of "C" Injury		52-53
Design		60	Number of "D" Injury		54-55
Facilities		61	Number of "E" Injury		56-57
Special Date & Cond.	825	62-66	Location	A5ELC	63-66
Type of Flight Hazard		69	Facility Date		69-74
Pri. Cause/Available Info. or Pil Hazard or Or Acc?		70			
Causal Fac for Pri-Cause		71-72			
Carrier Mail Number		73-74			
No Personnel Card ("R")		80			

PERSONNEL STATISTICS (Card No. 2)

File Number →	641327	Rank/Rate		62-63	64-65	66-67	68-69	70-71	72-73	74-75
Name	(b)(6)	Service No.	5251A1E2	60-61	62-63	64-65	66-67	68-69	70-71	72-73
Age	16	17	18	19	20	21	22	23	24	25
File Number →	16	17	18	19	20	21	22	23	24	25

ACCIDENT DAMAGE	A	Part 1 Count	Part 2 Count	Part 3 Count	Part 4 Count	Part 5 Count	Part 6 Count	Part 7 Count	Part 8 Count	Part 9 Count	Part 10 Count
ACCIDENT INJURY											
PISCAL YEAR	2										
SPECIAL ATTN ("X")											
Model Code											

CODED 21 REVIEWED AD LOADED AD PUNCHED AD VERIFIED AD REVIEWED AD REPUNCHED AD

CODE SHEET REVIEWED BY CLASS DESK ANALYST _____ (Initials) _____ (Date)

3

Don't Count



Other Aircraft

7576	7718	75
21	76	2

Year	Month	Day	Type Occurrence Sequence	Damage Injury	Model Aircraft
2022	7	10	2	A	F921

Bureau Number

1	4	5	3	9	6
---	---	---	---	---	---

NARRATIVE NOTES

DURING RDZV #4 HAD TROUBLE KEEPING FLIGHT IN SIGHT DUE
SUN GLARE. SLID V SIDE TO SIDE V BELOW ATTEMPTING JOIN
RATE OF CLOSURE EXCESSIVE PULL UP $\frac{1}{2}$ TO RIGHT OF FORM.
CRANKED IN 60 DEG BANK TO STOP RELATIVE MOTION. MC
CONT ROLL INVERT STRUCK #1. BOTH EST \leftarrow 27M/300. TER WEEK

Prepared by

Reviewed

Punched

Verified

Notes to ILM: Route code sheet to Open File upon completion of Brief Cards

APR 04 1962

U. S. NAVAL AVIATION SAFETY CENTER
U. S. NAVAL AIR STATION
NORFOLK 11, VIRGINIA

NASC/111/ees
Ser: 1113
22 May 1962

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARAGRAPH 70, OPNAVINST P3750.6D

From: Commander, U. S. Naval Aviation Safety Center
To: Commanding Officer, Fighter Squadron ONE TWO FOUR

Subj: VF-124 AAR ser 2-62 concerning FSU-2, BuNo 146975, and FSU-1,
BuNo 145396, accident occurring 27 February 1962, pilots

(b) (6)

1. The subject report and all endorsements thereon have been reviewed. The Naval Aviation Safety Center concurs with the comments and recommendations of the Aircraft Accident Board as modified by subsequent endorsers.
2. The cause of this accident has been recorded by the Center indicating the pilot (b) (6) as the single contributing factor.

(b) (6)

By direction

Copy to:
BUWPS (C-13) (2)
CMC (CODE AAP)
CINCPACFLT
COMFAIRSDIEGO
CGFIRSTMAW
COTHIRDMAW
OO, MAG 33
OO, NAS MIRAMAR
OO, VF-174
OO, LIGHTPHOTORON 63
BUWPSREP DALLAS
COMCVG-12
COMNAVAIRPAC

4

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARAGRAPH 70, OPNAVINST 3750.6D

5 APR 1962

FOURTH ENDORSEMENT on FITRON 124 AAR ser 2-62 concerning F8U-1/F8U-2
BUNOS 145306/146975 accident occurring 27 February 1962 pilots
1stLT (b) (6) and LTJG (b) (6)

From: Commander Naval Air Force, U. S. Pacific Fleet
To: Commander, U. S. Naval Aviation Safety Center

Subj: FITRON 124 AAR ser 2-62

1. Forwarded, concurring generally in the comments and recommendations
of the Aircraft Accident Board as modified by the first endorser.

a. The recommendation contained in paragraph 3 of the AAR will be
the subject of an NAVAIRPAC Safety Bulletin and an agenda item for area
safety council meetings.

b. The recommendation in paragraph 4 of the basic correspondence
is strongly concurred in. Standardization of placement of the survival
knife on the pilots equipment is considered a must in the interest of
reducing injuries sustained by pilots during ejection through snagging
of the knife and in the interest of locating the knife or an acceptable
shroud cutter so as to be accessible at all times.

2. The following administrative errors are noted:

a. The reporting custodian did not state when the last aircraft
accident prevention survey established by COMNAVAIRPACINST 3750.42
was held.

b. The reporting custodian did not state whether COMNAVAIRPAC Report
Symbol 3750.1 would be submitted.

c. Reporting custodian did not state whether any NATOPS Procedure
was violated or whether any changes should be promulgated.

3. For purposes of safety awards this accident is administratively
charged to FITRON 124.

(b) (6)

By direction

FF4-1/3750

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARAGRAPH 70, OPNAVINST 3750.6D

Copy to:
BUNOPS (C-13)
COMNAVAVNSAFECEN (2) (Airmail)
CNC (CODE AAF)
CINCPACFLT
COMPAIRSCINGO
COMPAIRTHAW
COMPAIRTHAW
CO MAG 33
CO HAS MIRAMAR
CO FITRON 124, 174
CO LIGHTPHOTORON 63
BUNOPS REP DALLAS

FF7/3750
Serial:
80/ 609

MAR 28 1962

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARAGRAPH 70, OPNAVINST 3750.6D

THIRD ENDORSEMENT on VF-124 AAR ser 2-62 concerning F8U-1/F8U-2 BuNo's
145396/146975 accident occurring 27 February 1962, Pilots 1/LT (b) (6)
and LTJG (b) (6)

From: Commander Fleet Air San Diego/Naval Air Bases, ELEVENTH Naval
District
To: Commander, U.S. Naval Aviation Safety Center
Via: Commander Naval Air Force, U.S. Pacific Fleet

Subj: VF-124 Aircraft Accident Report ser 2-62 of 27 February 1962;
forwarding of

1. Forwarded, concurring in the comments and recommendations of the
Aircraft Accident Board and in the remarks contained in the subsequent
endorsements.

(b) (6)

CHIEF OF STAFF

Copy to:
NAVAVSAPCEN
BUWEP3
CINCPACFLT
CMC (Code AAP)
BUWEP3REP DALLAS
CO, NAS MIRAMAR
1st, 3rd MAW
CO, VF-124
CO, VF-174
CO, VFP-63
MAAG-33
COMCVG-12

ORIGINAL

CO: VO-12/10: jrl
3750
Ser: 00/ 474
23 MAR 1962

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARAGRAPH 70 OF OPNAV INST 3750.6D

SECOND ENDORSEMENT on VF-124 AAR 2-62 concerning F8U-1/F8U-2 BuNo's
145396/146975 accident occurring 27 February 1962, Pilots 1/LT (b) (6)
and LTJG (b) (6)

From: Commander Carrier Air Group TWELVE
To: Commander U.S. Naval Aviation Safety Center
Via: (1) Commander Fleet Air San Diego
(2) Commander Naval Air Force, U. S. Pacific Fleet.

Subj: VF-124 Aircraft Accident Report 2-62; forwarding of

1. Forwarded, concurring with the comments and recommendations of the
Aircraft Accident Board and the first endorser.

Paul F. Stevens
PAUL F. STEVENS

Copy to:
NAVSAFECEN (2)
BUMPS
CINCPACFLT
COMNAVAIRPAC
COMFAIRSDIEGO
CNC (Code AAP)
BUMPSREP DALLAS
CO, NAS MIRAMAR
1st, 3rd MAI
CO, VF-124
VF-174, VFP-63, MAAG-33

50
ORIGINAL

ORIGINAL

VF-124:20:abf
3750
Ser 274
15 March 1962

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH PARAGRAPH 70, OPNAVINST 3750.6D

FIRST ENDORSEMENT on VF-124 AAR 2-62 concerning F8U-1/F8U-2, BUNO
145396/146975, accident occurring 27 February 1962, Pilots 1/LT (b) (6)
LTJG (b) (6)

From: Commanding Officer, Fighter Squadron ONE TWO FOUR (VF-124)
U. S. Naval Air Station, Miramar 45, California
To: Commander, Naval Aviation Safety Center
Via: (1) Commander, Carrier Air Group TWELVE
(2) Commander, Fleet Air San Diego
(3) Commander, Naval Air Force, U. S. Pacific Fleet

Subj: VF-124 Aircraft Accident Report 2-62; forwarding of

1. Forwarded, concurring with the comments and recommendations of the
Aircraft Accident Board except as follows:

a. Comment b. lists limited experience as a contributing factor in this
accident but neglects to mention that other trainees of this replacement
squadron are capable of effecting the rendezvous maneuver safely at the same
experience level.

2. Marine Corps trainees are received in this command without any previous
record of flight performance. Consequently, these pilots are closely
observed by VF-124 instructor pilots for any weaknesses which would forecast
such an unsatisfactory performance as was demonstrated in this accident.
Unfortunately, no weakness sufficient to warrant investigative action had
been demonstrated by this pilot prior to the accident. Action has already
been taken to obtain flight performance jackets for Marine Corps pilots.

3. The prompt evasive action of the flight leader in all probability pre-
vented the destruction of four aircraft instead of two in this accident.

W. J. McVEY

Copy to:
COMNAVAVSAPCENT (2cc direct Air Mail)
BUWEP (1cc direct Air Mail)
CINCPACFLT
COMNAVPAIRPAC
COMFAIRSDIEGO
CMC (Code AAP)
COMCARAIRCGRU TWELVE
BUWEPREP DALLAS
CO, NAS MIRAMAR
1ST & 3RD MAW
VF-174, VFP-63, MAAG-33

19

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 70, OPNAVINST 3750.6D

ORIGINAL

AIRCRAFT ACCIDENT REPORT
OPNAV FORM 3750-1 (Rev. 12-59) PAGE 1SPECIAL HANDLING REQUIRED in accordance
with Para. 65, OPNAV INSTRUCTION 3750.6C

PART I - GENERAL

1. A/C ACCIDENT BOARD APPOINTED BY Commanding Officer, Fighter Squadron-124		2. DATE OF ACCIDENT 27 FEB 1962	TIME (LST) 1704	3. SERIAL NUMBER AAR 2-62
4. Commander, TO: U.S. Naval Aviation Safety Center		5. ENCLOSURES (1) MOR (Original only)		
6. VIA (1) Commanding Officer, PITRON 124		(2) Pilot's Statement		
(2) Commander, Carrier Air Group TWELVE		(3) Pilot's Statement		
(3) Commander, Fleet Air San Diego		(4) Flight Leader's Statement		
(4) Commander, Naval Air Force, U.S. PacFlt		(5) Flight Member's Statement		
(5)		(6) Photo Fuselage NJ-433		
(6)		(7) Photo Fuselage NJ-408		
(7)		(8) Photo Vertical Fin NJ-408		
(8)		(9) (See attached sheet)		
7. REPORTING CUSTODIAN (if different than item 1, above) NA		8. ACTIVITY OPERATING A/C (if different than item 1, above) NA		
9. KIND OF FLIGHT 1AL	10. TIME OF DAY <input type="checkbox"/> DAWN <input checked="" type="checkbox"/> DAY <input type="checkbox"/> DUSK <input type="checkbox"/> NIGHT	11. LOCATION OF ACCIDENT 33° 16' N Long 116° 33' W 22nd Air Force Springs		12. ELEVATION ABOVE SEA LEVEL 27,000
13. PLACE OF LAST TAKE-OFF Touch & Go at MCAAS Yuma		14. CLEARED FROM NAS Miramar TO NAS Miramar		
15. TYPE CLEARANCE <input type="checkbox"/> VFR <input checked="" type="checkbox"/> VFR <input type="checkbox"/> DIVE <input checked="" type="checkbox"/> LOCAL <input type="checkbox"/> OPERATIONAL <input type="checkbox"/> AIRWAYS <input type="checkbox"/> DIRECT <input type="checkbox"/> OTHER (Specify)				
16. TIME IN FLIGHT 01:41	17. TYPE ACCIDENT A-1, 6-8 in air, collision	18. PHASE OF FLIGHT 4 in flight		
19. MODEL F8U-2	20. SERIAL NO. 146975	21. DAMAGE TO A/C <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H <input type="checkbox"/> I <input type="checkbox"/> J <input type="checkbox"/> K <input type="checkbox"/> L <input type="checkbox"/> M <input type="checkbox"/> N <input type="checkbox"/> O <input type="checkbox"/> P <input type="checkbox"/> Q <input type="checkbox"/> R <input type="checkbox"/> S <input type="checkbox"/> T <input type="checkbox"/> U <input type="checkbox"/> V <input type="checkbox"/> W <input type="checkbox"/> X <input type="checkbox"/> Y <input type="checkbox"/> Z	22. DOLLAR COST 999,000	23. AIRSPEED (Kts) 300
24. A/C WEIGHT 20,000		25. LIST MODEL, SER NO., REPORTING CUSTODIAN AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED (Complete on OPNAV FORM 3750-1 for each A/C involved)		
F8U-1 145396 VF-124 A				

1. NAME (Last, first and middle initials) PILOT (see remarks at time of accident)	2. GRADE LTJG	3. FILE NO. (b) (6)	4. DUTY STATION 1315	5. BRANCH OR SERVICE USNR	6. AGE 24	7. JRS OF USA 1	8. BILLET Pilot	9. POSITION Pilot	10. REPORT CODE E
COPILOT									

PERSONNEL	8. OBT - OPERATIONAL FLIGHT TRAINER		9. CPT - COCKPIT PROC. TRAINER		10. UNIT TO WHICH PERSONNEL ARE ATTACHED VF-124	11. TYPE INSTRUMENT CARD <input checked="" type="checkbox"/> STANDARD <input type="checkbox"/> SPECIAL
	AVAILABLE	USED	AVAILABLE	USED		
PILOT	YES	X	X	X	VF-124	<input checked="" type="checkbox"/> STANDARD <input type="checkbox"/> SPECIAL
	NO					
CO-PILOT	YES				VF-124	<input type="checkbox"/> STANDARD <input type="checkbox"/> SPECIAL
	NO					

ITEM	PILOT	CO-PILOT	ITEM	PILOT	CO-PILOT
ALL MODELS	353		CV LANDINGS DAY/NIGHT	12	
ALL MODELS IN LAST 12 MONTHS	251		FCLP LANDINGS DAY/NIGHT	89	
ALL MODELS IN LAST 3 MONTHS	21		INSTRUMENT HOURS LAST 3 MONTHS	1.1	
ALL SERIES THIS MODEL (Ann 79)	A/C 9.5		NIGHT HOURS LAST 3 MONTHS	0	
	OFT / CPT 2/1		TOTAL HELO. HRS. (Under AAR Only)	NA	
ALL SERIES THIS MODEL LAST 12 MONTHS	A/C 9.5		TOTAL JET HOURS (Under AAR Only)	315	
	OFT / CPT 2/1		LAST FLIGHT, ALL SERIES THIS MODEL	DATE 26 FEB 1962	
ALL SERIES THIS MODEL LAST 3 MONTHS	A/C			TIME 1.8	
	OFT / CPT				

NAME (Last, first and middle initials)	DNA	GRADE	FILE/SERVICE NO.	ORG. TO WHICH ATTACHED	DATE	BILLET	REPORT CODE
1. NA							
2.							
3.							
4.							
5.							

SPECIAL HANDLING REQUIRE IN ACCORDANCE WITH PARA 70, OPNAVINST 3750.6D

PAGE 2

1. CEILING 0	2. VISIBILITY 35	3. RELATIVE WIND (SEE INST IN) 290M REL / 10 KTS	4. TEMPERATURE DAY 52 RUNWAY 52	5. DEW POINT 30	6. ALTITUDE SETTING 30.11
-----------------	---------------------	---	---------------------------------------	--------------------	------------------------------

7. OTHER WEATHER CONDITIONS (include aloft, icing levels, sea state, etc., if pertinent to accident)

CAVU at altitude - weather not a factor

✓	FACTOR	✓	FACTOR	✓	FACTOR
	PILOT		LANDING SIGNAL OFFICER		MATERIAL FAILURE OR MALFUNCTION
	CREW	X	OTHER PERSONNEL (Specify) Mid-Air Collision Victim		DESIGN
	SUPERVISORY PERSONNEL		ADMINISTRATIVE		ROLLING AND PITCHING DECK/ ROUGH SEAS
	MAINTENANCE PERSONNEL		AIRPORT OR CARRIER FACILITIES		UNDETERMINED
	SERVICING PERSONNEL		WEATHER		OTHER (Specify)

FOR ACCIDENTS ABOARD DEPLOYED CARRIER (Complete following Section on Pilot)

1. DATE DEPLOYED NA	2. DAY - HOURS/LANDINGS LOGGED SINCE DEPLOYED NA	3. DAY - HOURS/LANDINGS LOGGED LAST 30 DAYS NA
4. INSTRUMENT HRS. LOGGED SINCE DEPLOYMENT NA	5. NIGHT - HOURS/LANDINGS LOGGED SINCE DEPLOYED NA	6. NIGHT - HOURS/LANDINGS LOGGED LAST 30 DAYS NA

PART II - MAINTENANCE, MATERIAL AND FACILITIES DATA

1. AC HISTORY	DATE OF MANUFACTURE	SERVICE TOUR	MONTHS IN THIS TOUR	TOTAL NO OF OVERHAULS	FLIGHT HRS SINCE LAST OVERHAUL	FLIGHT HRS SINCE ACCEPTANCE	TYPE CHECK LAST PERFORMED	FLIGHT HOURS SINCE LAST CHECK	NO. OF DAYS SINCE LAST CHECK
	1-29-60	2	5	1	251.1	686.2	Intermediate	104.3	39
2. ENGINE HISTORY	ENGINE MODEL	ENGINE SERIAL NO.							
1	6-1-59	J-57-P15	P631364	3	234.4	798.2	Major	104.3	39
2									
3									
4									
a. DID FIRE OCCUR?							b. DID EXPLOSION OCCUR IN FLIGHT?		
<input type="checkbox"/> BEFORE ACCIDENT <input checked="" type="checkbox"/> AFTER ACCIDENT <input type="checkbox"/> DID NOT OCCUR							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
c. CHECK IF APPLICABLE				d. HAS DIR BEEN REQUESTED?		e. FAILED COMPONENTS INVOLVED			
<input type="checkbox"/> AMP/FUR SERIAL				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		None			
CHECK ITEMS PRESENT IN THIS ACCIDENT									
a. <input type="checkbox"/> A/C DESIGN			d. <input type="checkbox"/> UNDETERMINED			g. <input type="checkbox"/> SURFACE FACILITIES			
b. <input type="checkbox"/> A/C EQUIPMENT			e. <input type="checkbox"/> TECHNICAL INSTRUCTION			h. <input type="checkbox"/> HUMAN ENGINEERING (e.g., Cockpit configurations, etc.)			
c. <input type="checkbox"/> MAINTENANCE			f. <input type="checkbox"/> OTHER (Specify)						
a. ALTITUDE AT MALFUNCTION		b. AIR SPEED		c. OPERATING TEMP		d. WEIGHT OF A/C		e. CG (% MAC)	
NA		NA Kts		NA		NA		NA	
f. EVIDENCE OF FUEL CONTAMINATION					g. CAUSE OF ENGINE FAILURE OR FLAMEOUT				
NA					NA				
h. FUEL CONTROL REGULATOR/DISTRIBUTOR (See para 70, OPNAVINST 3750.6D)							i. LATERAL STORES ABOARD A/C		
NA							NA		

(If additional space is necessary, attach additional sheets)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 70, OPNAVINST 3750.6D

AIRCRAFT ACCIDENT REPORT

PART II - MAINTENANCE, MATERIAL AND FACILITIES DATA (Continued)

1. GENERAL. ☒ BASIC FACILITIES INVOLVED. DESCRIBE EFFECT ON ACCIDENT IN THE ANALYSIS SECTION OF THE REPORT

a. CLEARANCE AUTHORITY	i. WATER LANDING AREA	q. CRASH AND RESCUE
b. FLIGHT PLANNING INFORMATION SOURCE	j. APPROACH ZONE	r. SEARCH AND RESCUE
c. LANDING AIDS (GCA, CCA, ILS, etc.)	k. END ZONE (Over run)	s. CATAPULT
d. TRAFFIC CONTROL TOWER (Field or Ship)	l. SHOULDERS	t. ARRESTING GEAR (Carrier)
e. APPROACH AND ENROUTE AIDS TO NAVIGATION	m. TAXIWAY NA	u. BARRIER OR BARRICADE (Field or Ship)
f. RUNWAY WATCH	n. PARKING AREA	v. FLIGHT DECK
g. LANDING SIGNAL OFFICER	o. EMERGENCY ARRESTING GEAR (Runway)	w. MIRROR
h. RUNWAY	p. A/C SERVICING, HANDLING AND DIRECTING (Field or Ship)	x. OTHER (Specify) None

b. EQUIPMENT INVOLVED:	<input type="checkbox"/> CATAPULT	d. PRESSURE SETTINGS	e. WIND OVER DECK	f. RELATIVE HEADWIND	g. APPROACH SPEED (50% - 12 READING)
	<input type="checkbox"/> ARRESTING GEAR				

1. MARK NUMBER	2. MODEL NUMBER	3. LOCATION ON SHIP	4. LAUNCHING BRIDLE AND CONFIGURATION USED
----------------	-----------------	---------------------	--

1. CATAPULT / ARRESTING GEAR BULLETINS OR HOMOGRAMS USED

A. THIS PORTION SHALL BE COMPLETED WHENEVER (1) A MAJOR AIRCRAFT ACCIDENT INVOLVES ARRESTING GEAR, BARRIER AND/OR BARRICADE EQUIPMENT, OR (2) AN AIRCRAFT ACCIDENT INVOLVES MALFUNCTIONING OF ARRESTING GEAR, BARRIER AND/OR BARRICADE EQUIPMENT MINOR ACCIDENTS OR ROUTINE DAMAGE TO CABLES, WELDINGS AND OTHER EXHAUSTIBLE COMPONENTS NEED NOT BE REPORTED.

ENGAGED	DECK RUNOUT (FT)	RAM TRAVEL (IN)	CONTROL VALVE SETTINGS		ACCUMULATOR PRESSURE (PSI)	COMMENTS (For cable failure specify number of landings and months in service)
			CONSTANT PRESSURE			
			DOSE (PSI)	RATIO		
DECK PENDANT	NA					
DECK PENDANT						
BARRIER						
BARRIER						
BARRICADE						

PART I	SECTION	ITEM	PART III REMARKS (Continue on additional sheets)	COPY DISTRIBUTION:
I	A	5	See attached sheet for enclosures and distributions	JCC. NAVY/NAFECEN DIRECT (AM) 1CC. BUREAU DIRECT (AM) 1cc CINCPACFLT 1cc COMNAVAIRPAC 1cc COMFAIRSDIEGO 1cc CMQ (Code AAP) 1cc COMCVO TWELVE 1cc BUREAU/REP DALLAS 1cc CO NAS Miramar 1cc 1st. 3rd MAW
GOVERNMENT PROPERTY			PRIVATE PROPERTY Preliminary estimate \$5000.00	DATE SUBMITTED TO C. O. 12 March 1962
None				
SIGNATURES OF THE BOARD				
SEARCH NUMBER	(b) (6)		MEMBER (b) (6)	UNIT BILLET
	(b) (6)		Administrative Officer	UNIT BILLET
	(b) (6)		LT, (MC) USNR	UNIT BILLET
	(b) (6)		MEMBER (b) (6)	UNIT BILLET

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 70, OPNAVINST 3750.6D

PART I - GENERAL

1. A/C ACCIDENT BOARD APPOINTED BY Commanding Officer, Fighter Squadron 124		2. DATE OF ACCIDENT 27 FEB 1962	TIME (LST) 1704U	3. SERIAL NUMBER AAR 2-62
4. Commander, TO: U.S. Naval Aviation Safety Center		5. ENCLOSURES (1) (a) (See other sheet)		
6. VIA (1) Commanding Officer, FITRON 124		(b)		
(2) Commander, Carrier Air Group TWELVE		(c)		
(3) Commander, Fleet Air San Diego		(d)		
(4) Commander, Naval Air Force, U.S. PacFlt		(e)		
(5)		(f)		
(6)		(g)		
7. REPORTING CUSTODIAN (if different than item 1. above) Same		8. ACTIVITY OPERATING A/C (if different than item 7.) Same		
9. KIND OF FLIGHT 1A1	10. TIME OF DAY <input type="checkbox"/> DAWN <input checked="" type="checkbox"/> DAY <input type="checkbox"/> DUSK <input type="checkbox"/> NIGHT	11. LOCATION OF ACCIDENT Lat 33° 16' N Long 116° 22' W Borrego Springs		12. ELEVATION ABOVE SEA LEVEL 27,000 ft
13. PLACE OF LAST TAKE-OFF Touch and Go at MCA/S Yuma		14. CLEARED FROM NAS Miramar TO NAS Miramar		
15. TYPE CLEARANCE <input type="checkbox"/> IFR <input checked="" type="checkbox"/> VFR <input type="checkbox"/> DFR <input checked="" type="checkbox"/> LOCAL <input type="checkbox"/> OPERATIONAL <input type="checkbox"/> AIRWAYS <input type="checkbox"/> DIRECT <input type="checkbox"/> OTHER (Specify)				
16. TIME IN FLIGHT 01:41 Min	17. TYPE ACCIDENT A-1, 6-8 in air, ejection	18. PHASE OF FLIGHT 4 in flight		
19. MODEL F8U-1	20. SERIAL NO. 145396	21. DAMAGE TO A/C <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F	22. DOLLAR COST 1,109,000	23. AIRSPEED (KMH) 300
24. A/C WEIGHT 19,500#		25. LIST MODEL, SER. NO., REPORTING CUSTODIAN AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED (Complete on OPNAV FORM 3750-1 for each A/C involved)		
F8U-2 146975 VF-124 A				

1. NAME (Last, first and middle initials) PILOT (for accidents at sea of accident)	2. GRADE 1/LT	3. FILE NO. (b) (6)	4. DESIG. 7398	5. BRANCH OR SERVICE USMCR	6. AGE 29	7. YRS OF EXP. DATA 1	8. BILLET Pilot	9. POSITION Pilot	10. FLIGHT CODE E
CO-PILOT									

PERSONNEL	6. OPT - OPERATIONAL FLIGHT TRAINER		9. CPT - COCKPIT PROC. TRAINER		10. UNIT TO WHICH PERSONNEL ARE ATTACHED VF-124	11. TYPE INSTRUMENT CARD <input checked="" type="checkbox"/> STANDARD <input type="checkbox"/> SPECIAL
	AVAILABLE	USED	AVAILABLE	USED		
PILOT	YES	X	X	X		
	NO					
CO-PILOT	YES					
	NO					

SECTION B - PERSONNEL DATA PILOT EXPERIENCE IN HOURS	12. ITEM		PILOT	CO-PILOT	ITEM		PILOT	CO-PILOT
	ALL MODELS		395		CY LANDINGS DAY/NIGHT		12	
	ALL MODELS IN LAST 12 MONTHS		231		FCLP LANDINGS DAY/NIGHT		127	
	ALL MODELS IN LAST 3 MONTHS		31		INSTRUMENT HOURS LAST 3 MONTHS		18	
	ALL SERIES THIS MODEL (Last 12 Mo)	A/C	9		NIGHT HOURS LAST 3 MONTHS		2	
		OPT / CPT	3/3		TOTAL HELD. HRS. (Feb. 448 Only)		NA	
	ALL SERIES THIS MODEL LAST 12 MONTHS	A/C	9		TOTAL JET HOURS (Jan 448 Only)		225	
		OPT / CPT	3/3		LAST FLIGHT, ALL SERIES THIS MODEL		DATE 26 FEB 1962	
13. NAME (Last, first and middle initials)	DNA	GRADE	FILE/SERVICE NO.	ORG. TO WHICH ATTACHED	INSTRUMENT CODE	BILLET	FLIGHT CODE	
	1. NA							
	2.							
	3.							
	4.							

PAGE 5

1. CEILING Clear	2. VISIBILITY 35	3. RELATIVE WIND (SEE INST.) 290° REL / 10 KTS	4. TEMPERATURE DAY 52 NIGHT 52	5. DOW POINT 30	6. ALTIMETER SETTING 30.11
---------------------	---------------------	---	--------------------------------------	--------------------	-------------------------------

7. OTHER WEATHER CONDITIONS (include aloft, icing levels, and state, etc., if pertinent to accident)

CAVU at altitude weather not a factor

✓	FACTOR	✓	FACTOR	✓	FACTOR
X	PILOT		LANDING SIGNAL OFFICER		MATERIAL FAILURE OR MALFUNCTION
	CREW		OTHER PERSONNEL (Specify)		DESIGN
	SUPERVISORY PERSONNEL		ADMINISTRATIVE		ROLLING AND PITCHING DECK/ ROUGH SEAS
	MAINTENANCE PERSONNEL		AIRPORT OR CARRIER FACILITIES		UNDETERMINED
	SERVICING PERSONNEL		WEATHER		OTHER (Specify)

FOR ACCIDENTS ABOARD DEPLOYED CARRIER (Complete following Section on Pilot)

1. DATE DEPLOYED NA	2. DAY - HOURS/LANDINGS LOGGED SINCE DEPLOYED	3. DAY - HOURS/LANDINGS LOGGED LAST 30 DAYS
4. INSTRUMENT HRS. LOGGED SINCE DEPLOYMENT	5. NIGHT - HOURS/LANDINGS LOGGED SINCE DEPLOYED	6. NIGHT - HOURS/LANDINGS LOGGED LAST 30 DAYS

PART II - MAINTENANCE, MATERIAL AND FACILITIES DATA

1. A/C HISTORY	DATE OF MANUFACTURE	SERVICE TOUR	MONTHS IN THIS TOUR	TOTAL NO. OF OVERHAULS	FLIGHT HRS SINCE LAST OVERHAUL	FLIGHT HRS SINCE ACCEPTANCE	TYPE CHECK LAST PERFORMED	FLIGHT HOURS SINCE LAST CHECK	NO. OF DAYS SINCE LAST CHECK	
	7-23-58	3	13	2	402.1	943.3	Intermediate	73.8	53	
		ENGINE MODEL	ENGINE SERIAL NO.							
2. ENGINE HISTORY	1	2-25-57	J57-P4	P608170	1	204.3	650.8	Intermediate	73.8	53
	2									
	3									
	4									

a. DID FIRE OCCUR?

☐ BEFORE ACCIDENT☒ AFTER ACCIDENT☐ DID NOT OCCUR

b. DID EXPLOSION OCCUR IN FLIGHT?

☐ YES☒ NO

c. CHECK IF APPLICABLE

☐ AMP FOR SERIAL

d. HAS D/R BEEN REQUESTED?

☐ YES☒ NO

e. FAILED COMPONENTS INVOLVED

None

CHECK ITEMS PRESENT IN THIS ACCIDENT

a. ☐ A/C DESIGNd. ☐ UNDETERMINEDg. ☐ SURFACE FACILITIESb. ☐ A/C EQUIPMENTe. ☐ TECHNICAL INSTRUCTIONh. ☐ HUMAN ENGINEERING (e.g., Cockpit configurations, etc.)c. ☐ MAINTENANCEf. ☐ OTHER (Specify)

a. ALTITUDE AT MALFUNCTION

NA

b. AIR SPEED

NA

c. OPERATING TEMP

NA

d. WEIGHT OF A/C

NA

e. CG (% MAC)

NA

f. KIND OF FUEL

NA

g. FUEL PRESSURE

NA

h. EVIDENCE OF FUEL CONTAMINATION

NA

i. CAUSE OF ENGINE FAILURE OR FLAMEOUT

NA

j. FUEL CONTROL REGULATOR/CONTROLLER (List stock and ser. nos., give time since new or overhauled)

NA

k. EXTERNAL STORES ABOARD A/C

NA

(If additional space is necessary, attach additional sheets)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 70, OPNAVINST 3750.6D

AIRCRAFT ACCIDENT REPORT

OPNAV REPORT 3750-1

PART II - MAINTENANCE, MATERIAL AND FACILITIES DATA (Continued)

1. GENERAL. a. BASIC FACILITIES INVOLVED. DESCRIBE EFFECT ON ACCIDENT IN THE ANALYSIS SECTION OF THE REPORT

a. CLEARANCE AUTHORITY	i. WATER LANDING AREA	q. CRASH AND RESCUE
b. FLIGHT PLANNING INFORMATION SOURCE	j. APPROACH ZONE	r. SEARCH AND RESCUE
c. LANDING AIDS (GCA, CCA, ILS, etc.)	k. END ZONE (Over run)	s. CATAPULT
d. TRAFFIC CONTROL TOWER (Field or Ship)	l. SHOULDERS	t. ARRESTING GEAR (Carrier)
e. APPROACH AND ENROUTE AIDS TO NAVIGATION	m. TAXIWAY	u. BARRIER OR BARRICADE (Field or Ship)
f. RUNWAY WATCH	n. PARKING AREA	v. FLIGHT DECK
g. LANDING SIGNAL OFFICER	o. EMERGENCY ARRESTING GEAR (Runway)	w. MIRROR
h. RUNWAY	p. A/C SERVICING, HANDLING AND DIRECTING (Field or Ship)	x. OTHER (Specify) None

2. EQUIPMENT INVOLVED

☐ CATAPULT

n. PRESSURE SETTINGS

o. WIND OVER DECK

p. RELATIVE HEADING

q. APPROACH SPEED (SPN 12 READING)

☐ ARRESTING GEAR

1. MARK NUMBER

2. MODEL NUMBER

3. LOCATION ON SHIP

4. LAUNCHING BRIGLE AND CONFIGURATION USED

5. CATAPULT / ARRESTING GEAR BULLETINS OR HOMOGRAMS USED

6. THIS PORTION SHALL BE COMPLETED WHENEVER (1) A MAJOR AIRCRAFT ACCIDENT INVOLVES ARRESTING GEAR, BARRIER AND/OR BARRICADE EQUIPMENT (1) OR (2) AN AIRCRAFT ACCIDENT INVOLVES MALFUNCTIONING OF ARRESTING GEAR, BARRIER AND/OR BARRICADE EQUIPMENT. MINOR ACCIDENTS OR ROUTINE DAMAGE TO CABLES, WELDINGS AND OTHER EXPENDABLE COMPONENTS NEED NOT BE REPORTED.

ENGAGED	DECK RUNOUT (FT)	RAM TRAVEL (IN)	CONTROL VALVE SETTINGS		ACCUMULATED OR PRESSURE (PSI)	COMMENTS (For cable failure specify number of landings and marks in service)
			CONSTANT PRESSURE			
			DOWN (PSI)	RATIO		
DECK PENDANT	NA					
DECK PENDANT						
BARRIER						
BARRIER						
BARRICADE						

PART SECTION	ITEM	PART III REMARKS (Continued on Additional sheets)	COPY DISTRIBUTION
1	A	5	200 NAVJAG/SECNAV DIRECT 100 BUWEP/SECNAV DIRECT
		See other sheet	See other sheet

COST DAMAGE TO:

GOVERNMENT PROPERTY

None

PRIVATE PROPERTY

See other sheet

DATE SUBMITTED TO C. G.

12 March 1962

SENIOR MEMBER

(b) (6)

1. SIGNATURE OF THE BOARD

MEMBER

(b) (6)

USN

(b) (6)

UNIT BILLET

(b) (6)

UNIT BILLET

LT (MC) USN

UNIT BILLET

PART V - THE ACCIDENT

At approximately 1525 uniform on 27 February 1962, LTJG (b) (6) and 1/LT (b) (6) took off from NAS Miramar as number 2 and 3 men of a scheduled four plane formation training flight. The flight leader was LT (b) (6) and the number 4 man was 1/LT (b) (6). The flight progressed in a normal manner through "finger four", instrument parade, break-up and rendezvous and tactical wing maneuvers. During the course of the tactical wing practice, some swapping of positions in the flight occurred so that as the flight finally joined in parade prior to entering the break for touch and go practice at MCAAS Yuma, the order became LT (b) (6) (1), LTJG (b) (6) (2), 1/LT (b) (6) (4) and 1/LT (b) (6) (3). After a break-up and two touch and go landings at MCAAS Yuma, LT (b) (6) directed the flight to make a running rendezvous enroute to Miramar via El Centro. LTJG (b) (6) joined on the starboard wing in parade, and then LT (b) (6) advised 1/LTs (b) (6) and (b) (6) that the rendezvous point would be on the 290° radial of El Centro at 30 miles.

After reaching the designated rendezvous point, LT (b) (6) proceeded to purge his wing fuel tank, hoping the remaining fuel vapor would attract attention and facilitate the rendezvous. He also noticed that the flight was closing a restricted area and again changed the rendezvous point to the 290° radial of El Centro at 40 miles. After reaching this point, he set up a standard port orbit and after about 80° of turn 1/LT (b) (6) joined the flight in right echelon, then moved over to the port wing. After approximately 180° of turn, 1/LT (b) (6) sighted the #3 man (1/LT (b) (6)) at the 5 O'clock position. At this time 1/LT (b) (6) broadcast, "Roger, have you".

1/LT (b) (6) passed under the formation, to the inside of the turn. He states that he was having some difficulty keeping the flight in sight due to the setting sun. He maneuvered back and forth across and behind the formation in an attempt to minimize the sun glare and close the formation from astern. The last time he attempted to move across from left to right, he began to slide to the outside and was slightly behind the formation. He rolled into a steep left bank in an effort to stop the lateral relative motion. He inadvertently continued the roll to an inverted position and struck LTJG (b) (6) aircraft on the right side.

LTJG (b) (6) felt his aircraft pitch nose down and attempted to move his controls. Feeling no response, he elected to eject and pulled the face curtain. At the same time, 1/LT (b) (6) felt his aircraft begin a spinning motion and attempted anti-spin control procedures. He then heard LT (b) (6) transmitting, "Get out of it! Get out of it now!" and ejected. 1/LT (b) (6) experienced some difficulty in pulling the face curtain all the way and finally lunged forward in the seat to pull the curtain. The seat then fired normally and performed according to specification.

Prior to these events, LT (b) (6) had seen an aircraft on his starboard side, inverted, and had pulled up and banked sharply to the left to avoid collision. As he looked back, he saw the fuselage of one airplane, minus the entire wing, nose down below him. He immediately transmitted, "Get out of it! Get out of it now!" and the pilot of the wingless aircraft ejected. He then observed two parachutes descending and, in addition, the fire from an aircraft crash in the area north of Borrego Springs.

He switched to Emergency IFF and transmitted "MAYDAY" on guard.

Both pilots descended normally in their parachutes and landed in open desert country near Borrego Springs, California. They were picked up by civilians and taken to Borrego Springs county airport, then flown to NAS Miramar by Coast Guard UF. Both pilots were examined at the NAS Miramar dispensary and found uninjured.

The two aircraft impacted in uncontrolled flight in four major sections near the town of Borrego Springs. The entire wing of NJ-408, the fuselage of NJ-408, the starboard wing of NJ-433, and the fuselage and port wing of NJ-433 were the major subsections. Both canopies and both ejection seats fell in the general area.

A secondary power line was severed and a vineyard was damaged by the fuselage of NJ-408. No other damage and no personal injury was incurred.

PART VI - DAMAGE TO THE AIRCRAFT

Both aircraft sustained Alfa damage as a result of the mid-air collision and subsequent impact with the ground.

A. The inflight damage consisted of:

(1) Complete separation of the entire wing from the fuselage of NJ-408. The right wing tip was bent upwards sharply for a distance of approximately two feet. The wing was torn loose from the pivot lugs and the wing incidence cylinder.

(2) The aft portion of the top of the vertical fin of NJ-408 was broken off. A portion of metal from the right wing of NJ-433 was found imbedded high on the right side of the vertical fin of NJ-408. The dorsal fin was torn just forward of the vertical fin, and there were numerous fluorescent red paint marks on the right side of NJ-408 above the UHT.

(3) The right wing of NJ-433 was bent down at the tip approximately two feet. The starboard wing had separated from the main body of the wing just outboard of the flap, approximately two feet from the fuselage. The entire outboard leading edge droop had been torn away from the wing and was not recovered.

B. The crash damage consisted of:

(1) Massive impact and fire damage to the fuselages of both aircraft from aft of the cockpit to just aft of the wing pivot fitting bulkhead. The cockpits and tail sections were recognizable but severely crushed. Fire broke out on impact and gutted the entire center section of both aircraft. There was no evidence of an inflight fire in either aircraft.

(2) The separated wing of NJ-408 and the starboard wing of NJ-433 sustained little damage due to ground impact. No fire broke out in either wing.

The aircraft have been turned over to COMNAVS Eleventh Naval District for salvage.

PART VII - THE INVESTIGATION

The location of the three known portions of the crash was verified by the Safety Officer in an aircraft the morning following the accident. The entire accident board then drove to the scene of the accident. The crash was apparently located in three separate areas, however superficial investigation revealed the possibility of a missing starboard wing from NJ-433. Impending darkness curtailed a detailed examination until the following morning. Investigation of the wreckage of NJ-433 the following morning verified the fact that the starboard wing was indeed missing. An aerial search the same afternoon located the missing wing. The accident board arrived at the crash site the next morning and completed the preliminary investigation. The aircraft was then released to salvage.

The fuselages of both aircraft were destroyed by fire from the wing pivot fitting rib forward to the aft bulkhead of the cockpit. (Encl: 6-7) The wing of NJ-408 though completely separated from the aircraft, was in relatively good condition as were the two sections of the wing from NJ-433. No evidence of inflight fire was discovered.

The wing tips and vertical fins of both aircraft were painted with high visibility red paint. The national star insignias are located in the conventional spots, i. e., on both sides of the fuselage aft of the cockpit, the lower surface of the starboard wing, and upper surface of the port wing.

Red paint marks were discovered on the starboard side of the vertical fin and dorsal fin of NJ-408. (Encl: 8) Severe inflight damage was detected on the dorsal fin. (Encl: 9) A piece of metal, foreign to the rudder structure and identified as wing structure, was discovered in the vertical fin of NJ-408. The rear portion of the top of the vertical fin of NJ-408 sustained inflight damage. (Encl: 10) The red paint marks, the damage to the vertical and dorsal fins and the piece of wing metal indicate that a collision between the wing of NJ-433 and the tail area of NJ-408 occurred in flight.

The starboard wing tip of NJ-408 was bent up by a collision inflight. This fact was verified by ground scars. The ground scar was caused by the wing of NJ-408 striking the ground leading edge first with the starboard half making initial contact. The resulting ground scar is in the form of a narrow, straight trough with a 60° curve approximately two feet from the starboard end. (Encl: 11) This substantiates the conclusion that the starboard wing tip was, in fact, bent upward prior to impact with the ground. The starboard wing tip of NJ-408 had red white and blue paint marks on the curled up portion. These marks had to come from the star insignia on the fuselage of NJ-433. The paint marks and ground collision marks indicate a collision between the fuselage (in the area of the star insignia) of NJ-433 and the wing tip of NJ-408.

The port wing of NJ-433 was virtually intact and showed no evidence of inflight damage (Encl: 12).

The starboard wing experienced extensive damage to the wing tip and leading edge which could have only occurred in flight. This statement is corroborated by the fact that no metal fragments were found in the wing impact area (Encl: 13) and red paint marks were found on the starboard wing. (Encl: 14) The damage to the leading edge therefore occurred inflight.

Although the wing of NJ-408 was practically intact the starboard droop and the starboard flap were missing. The droop was subsequently discovered at a location remote from the impact area. The missing droop and flap verify inflight damage to the starboard wing of NJ-408.

The starboard wing hinge pivot fitting of NJ-408 failed as a result of a load imposed on the rear of the starboard wing. (Encl: 15) The wing actuating rod failed due to shear loads imposed by counter-clock wise rotation of the wing about the aircraft yaw axis (Encl: 16) The port wing hinge pivot fitting remained intact, but the rotation of the wing tore the rib supporting the fitting out of the aircraft as the wing separated completely from the fuselage.

The damage to the leading edge of the starboard wing of NJ-433, the paint marks on the wing, the sequence of wing support failure, and the damage to the trailing edge of the starboard wing of NJ-408 indicate the collision of the starboard wing of NJ-433 with the trailing edge of the starboard wing of NJ-408. The concentration of damage on the starboard side of both aircraft establishes the fact that NJ-433 was inverted at the moment of collision.

Initial impact was probably the fuselage of NJ-433 against the wing tip of NJ-408 (Encl: 17). NJ-433 was in a near inverted position, rolling left and ascending. The second impact was between the starboard wing tip of NJ-433 and the tail area of NJ-408, with NJ-433 in an inverted attitude and over taking NJ-408. (Encl: 18) The third and disabling impact was between the leading edge of the starboard wing of NJ-433 and the trailing edge of the starboard wing of NJ-408. (Encl: 19) This blow probably caused the wing of NJ-408 to separate from the fuselage and simultaneously break off the starboard wing of NJ-433 at the junction of the flap and the aileron. The simultaneous failure of both wings is substantiated by the wreckage distribution. The more dense portions of the wreckage, (fuselages of NJ-408 and NJ-433), were located to the north west. The entire wing of NJ-408 was located approximately 1 1/2 air miles south east of the fuselage while the starboard wing of NJ-433 was located 2 1/2 miles to the south east. The wreckage should be distributed along a north-west, south-east line, if the separation of the pieces occurred simultaneously, since the wind at altitude was from the north west. The wreckage distribution does lie about this line and thus verifies the theory that all pieces separated at nearly the same instant. (Encl: 20).

DATA CONCERNING THE PILOTS

1/LT (b) (6) is TAD to VF-124 for training in the F8U and is scheduled for an 80 hour syllabus in the aircraft. He had completed six familiarization flights and one formation flight prior to the flight in question for a total of 9 hours in the aircraft. This flight was to be his second formation flight. During these flights, (b) (6) had received a total of twelve below average marks out of a total of 73 grades. Ten of these below average grades concerned his performance in FAN stage. These were mainly given for below average handling of the aircraft in the landing pattern. The last two below average marks were given on his first formation flight and were; (1) "Lost flight as number #2 man in a CV break up and rendezvous" (2) "Flies too far aft of bearing and overlaps wings in parade".

On the hop during which the collision occurred, the instructor commented that on two practice rendezvous (b) (6) had over-shot to the outside, was acute with a high closure rate, and that he had flown rough parade after the initial joinup.

LTJG (b) (6) is attached to VF-124 as a Fleet Replacement Pilot scheduled for the 100 hour syllabus in the aircraft. He had previously flown eight flights in the aircraft for a total of 9.5 hours. These flights included six completed FAM flights, one incomplete FAM flight, and one instrument flight. He had received eight below average marks out of a total of 102 grades in his previous flights. All below average marks were for poor handling of the aircraft in the landing pattern.

Both pilots had received the normal course of ground school instruction which includes a one week NAMD course and approximately eight days of lectures presented by squadron instructors. These first intensive days are then followed by half day flight and half day ground school. Specific lectures given both pilots prior to this accident included (1) Normal flight procedures (2) inflight emergencies (3) Spin recovery techniques (4) Basic formation in the F8U, and a thorough briefing and physical checkout on the Martin-Baker ejection seat. A considerable amount of the formation lecture is devoted to the importance of smooth flying and avoiding high closure rates in proximity to other aircraft.

PART VIII - ANALYSIS

In analyzing this accident it must be assumed that the primary cause factor was pilot technique aggravated by lack of experience and impaired visibility due to the position of the sun.

A. Personnel Factors:

The pilots involved in the accident displayed average progress through the syllabus to this point. It is common for most inexperienced students to have some difficulty in becoming accustomed to the handling characteristics of the F8U in the landing pattern, and for this reason, the board attaches little importance to the sub-par performance of 1/LT (b) (6) and LTJG (b) (6) in the landing pattern. 1/LT (b) (6) had received below average grades on his formation one for rendezvous technique and for losing sight of the flight. During the flight in question he made two practice rendezvous that resulted in an acute position with a high rate of closure. At the time of the accident neither pilot had accumulated enough time in the aircraft to display any tendencies or trends. The instance of 1/LT (b) (6) losing the formation the previous flight is not unusual, and neither are acute rendezvous in early stages of the formation syllabus. The board considered these adverse grades to be so common for inexperienced pilots that they were properly regarded as no cause for excessive alarm prior to the accident.

B. Supervisory Factors:

There were no supervisory factors contributing to the cause of this accident. Both pilots had received ground school lectures commensurate with their stage in the flight syllabus. The entire flight had been briefed one hour prior to take-off by the flight leader, LT (b) (6). LT (b) (6) is the Squadron Standardization Officer, and enjoys a well deserved reputation for thorough briefing techniques and precise execution of the flight syllabus. The only area of supervisory factor open to discussion is the establishment of the rendezvous circle in such a position that the sun was a factor. At 1700 during this time of year in California, the sun is extremely low on the southwestern horizon. It is considered that all members of the flight were exposed to the same hazards of sun blindness. It would have been impossible to establish a rendezvous circle which did not involve sun blindness in some sectors; therefore, the board concludes that although the sun may have been a factor in 1/LT (b) (6) erratic gyrations and losing sight of the formation, it is not a matter of supervisory error. 1/LT (b) (6) conclusion that he was in a normal spin was a natural one for a pilot at his stage of training. He attempted anti-spin procedures not realizing his starboard wing was missing. He had not completed the anti-spin procedures when LT (b) (6) broadcast his order to "Get out of it". This message was actually meant for LTJG (b) (6) who had lost his radio as his entire wing separated, but was immediately complied with by 1/LT (b) (6) however, under the circumstances that later developed, the order to eject was in the best interest of all concerned. The fact that the starboard wing was missing was not substantiated until approximately 36 hours after the accident.

The flight was briefed and conducted in accordance with the approved VF-124 flight syllabus and the applicable portions of the NATOPS manual.

C. Material Failure or Malfunction:

The board considers that material malfunction or failure was not a factor in this accident.

In an effort to conclusively rule out control malfunction, both yaw packages were examined, bench tested, and found, excluding the crash damage, to function properly. Neither aircraft has any record of control malfunctions in either roll or yaw. Unfortunately, both roll packages were destroyed by fire and no tests could be performed. Neither pilot, however, complained of any control malfunction during the flight prior to the accident.

Although the members of the board have a combined F8U flight time of over 1500 hours, no member of the board has ever experienced, or has ever talked to, or heard of, any F8U pilot who has ever been subjected to any uncontrollable inputs from the roll stabilization systems. One member has extensive maintenance experience with the F8U in two squadrons. A common roll stab failure consists of the roll stab shutting itself off in conditions of heavy turbulence, jet wash, or snap maneuvers. A more common failure of the stabilization systems consists of yaw oscillations of varying degree which can be corrected by turning off the yaw stab. In this case, both yaw stabilization packages performed properly excluding crash damage, on a bench test after the accident.

The board takes issue with the statement contained in enclosure (2) pertaining to the hydraulic pressure within the PC-systems. Handbook limitations indicate an upper limit of 3200 PSI. Over pressure in this case however, is not deemed a cause factor of poor or erratic flight control response.

The board therefore concludes that all control movements in both aircraft were made by the pilots, and that the stabilization systems were operating properly at the time of collision. Both the aircraft were in good mechanical condition with no outstanding discrepancies. Both aircraft had been properly pre-flighted and "signed off" by qualified plane captains. All applicable service changes pertinent to this accident were installed.

D. Facilities:

All facilities of NAS Miramar, the Coast Guard Air Station, San Diego, and various radar facilities in the area were utilized in an expeditious and professional manner. There are no cause factors or discrepancies under facilities. HU-1 at NAAS Romo Field provided invaluable assistance in search and transportation for the accident board.

E. Personnel Equipment, Survival Equipment:

Both pilots were dressed in accordance with the latest VF-124 Instructions and applicable survival bulletins, i.e., helmet with Hardiman fittings and chin strap, orange flight suit, 2-3 cutaway G suit, torso harness, flight gloves and high top shoes.

Martin-Baker F-5 seats were installed in both aircraft and apparently functioned properly. An inspection of both seats, canopies, and the remains of the cockpits was conducted. No reason for 1/LT (b) (6) statement that the canopy of his aircraft fired early was found to exist. The canopy of 1/LT (b) (6) aircraft was recovered intact with no plexiglass broken, which tends to eliminate the possibility that the canopy fractured on contact with LTJG (b) (6) aircraft and caused the windblast 1/LT (b) (6) describes in his statement. The board considers that the most probable cause of 1/LT (b) (6) difficulty in pulling the curtain was the high transverse G forces that he was subjected to in the rapidly rotating aircraft after the right wing failed. 1/LT (b) (6) also complained that the drogue gun piston was flailing around as he rode the chute down and that it struck him several times. 1/LT (b) (6) helmet had several gouges across the back where the drogue gun piston had evidently struck the helmet. Numerous other AARs have stated that this piston does indeed swing back and forth in close proximity to the head of the man in the chute, and the West Coast Martin-Baker representative confirmed this fact. Most pilots have cut the piston off if it got in the way. This was the action followed by 1/LT (b) (6). The drogue gun line must be retained at its present length in order for the seat to function properly, however, the piston presents a definite mental and physical hazard to a pilot in the descending parachute.

Both pilots had seat pans with the AN/PRT-3 UHF transmitter beacon installed in accordance with BUMPS aviation clothing and survival bulletin 39-60. The PRT in 1/LT (b) (6) aircraft was hooked up completely and functioned normally. Due to the squadron's not having received and completely installed all of the PRT-3 components in all aircraft, the PRT-3 in LTJG (b) (6) aircraft was inoperative. The PRT-3 is set to operate as the pilot separates from the seat at an altitude of 10-13,000 feet and operates continuously on 243.0 MCS until shut off, or the battery runs dead. The PRT-3 in 1/LT (b) (6) aircraft functioned so efficiently that guard channel was unusable until it was shut off. The length of time that the PRT-3 was audible to remote ground stations was compromised due to the fact that ejection occurred over mountainous terrain, however, it was monitored by numerous local ground stations within a radius of 75-100 miles.

Both pilots released their seat packs at altitudes of 100-200 feet. This is in accordance with squadron survival training which recommends this maneuver over land in order to minimize leg injury on landing.

PART IX - COMMENTS

The cause factors of this accident were:

a. 1/LT (b) (6) in losing sight of the flight leader and the rendezvous group, was inadvertently placed in a very poor position from which to execute a rendezvous. His maneuvers to gain the number 4 position in the flight were erratic and were hampered to some extent by the position of the sun. His last attempt to effect rendezvous resulted in an extremely high closure rate between his aircraft and the rendezvous group. In an attempt to reduce the relative motion 1/LT (b) (6) increased his bank markedly, became disoriented, and rolled into inverted flight. While in an inverted and ascending attitude, 1/LT (b) (6) rolled up and into the starboard wing tip of NJ-433. Pilot factor is determined as the primary cause of this accident.

b. Limited experience as a pilot of high performance aircraft is considered a contributing factor. 1/LT (b) (6) had only 8.5 hours in type.

PART X - RECOMMENDATIONS

1. Pilots should be continually appraised of the hazards involved in an improperly executed rendezvous. The necessity of properly assessing the closure rate by keeping all aircraft in sight cannot be over-stressed. The pilot's statement attests to a poor scan pattern and lack of reference to the horizon which resulted in a phenomenon similar to "Target fixation". Pilot briefing must continually emphasize the insidious dangers which may arise during the rendezvous maneuver.
2. It is recommended that the PRT-3 beacon should be installed so as to actuate upon ejection rather than separation from the seat. This would allow ground stations extra time in which to take fixes on the parachuting pilots. In cases where the parachute descent is into mountainous territory, which is common on the West Coast; the time between chute opening at 10-13000 feet, and descent below line of sight UHF range would be so short as to preclude an adequate fix on the position of the pilot.
3. It is recommended that the Martin-Baker CO. investigate the possibility of disposing of, or otherwise safetizing the swinging drogue gun piston after main parachute deployment. 1/LT (b) (6)'s helmet had several gouges in the rear which indicated that the drogue gun piston was potentially capable of causing serious injury to an unprotected head. It is further recommended that the potential danger of the swinging drogue gun piston be re-emphasized to all pilots, and that the necessity for retaining the protective helmet till safely on the ground be stressed. In this same context, the advisability of removing the oxygen mask before striking the ground cannot be too strongly emphasized. A pilot rendered unconscious by ground impact can easily suffocate if the bail-out oxygen runs out before the pilot regains consciousness, since the A-13A oxygen mask with miniature regulator installed stops all flow of air unless a positive pressure is supplied to the regulator.
4. As an alternate method of alleviating the menace of the drogue gun piston swinging near the pilot's head, many pilots have simply cut the weight off and disposed of it. This is what 1/LT (b) (6) finally did. All pilots in VF-124 are required to carry survival knives, however the position in which these knives are carried varies considerably. In many cases it would not be possible for a pilot in a parachute to reach a knife enclosed in a scabbard on the back of his leg. For this reason it is recommended that small pocket size survival knives, with a switch blade type shroud cutter blade be purchased for use by pilots. These knives are compact enough to be mounted on the torso harness in a position readily accessible to the pilot in any position. Samples of the shroud cutter have been tested by this squadron and have proved to be very effective in cutting shroud lines and webbing. Their use in a water survival situation would prove invaluable in getting free of shroud lines.

STATEMENT OF THE PILOT 1/LT (b) (6) USMC, (b) (6) 1398 CONCERNING
VF-121, MAR 2-62 FBU-1/78U-2 BUNO 115396-116975 OCCURRING 27 FEBRUARY 1962

LT (b) (6) 1/LT (b) (6) LTJG (b) (6) and myself launched a formation
2 flight at 1530. The briefing prior to the flight was normal for the hop
and as outlined on the briefing card.

The aircraft assigned to me was N4-433. I checked the yellow sheets of
the previous flights noting the varied discrepancies. The two previous
complaints I checked closely were the brakes and a high hydraulic pressure.
Upon turn up and pre-flight, I noticed no discrepancies. Hydraulic pressure
for both P.C. systems was slightly over 3400 pounds, which was noted on the
previous hop. This is slightly higher than normal, but I have been told by
maintenance, within limits.

The flight was normal and flown as outlined on the briefing card.

I flew #3 position until approximately ten minutes before we went to
MCAS Yuma at which time I moved to #1, 1/LT (b) (6) taking #3 position.

The flight entered the traffic pattern at MCAS Yuma and each of us
made two touch and go landings.

We departed MCAS Yuma and attempted to rendezvous at the 0800 radial
of El Centro TACAN as briefed. I did not have sight of any member of the
flight during the time we left Yuma until 25 miles from El Centro. I saw
1/LT (b) (6) directly ahead of me and retained sight of him until he turned
into the sun over El Centro.

LT (b) (6) then established a new rendezvous point on the 30 mile fix
on the 290° radial of El Centro TACAN. I proceeded outbound on this radial
attempting to regain visual contact with the other members of the flight. The
rest of the flight at this time had joined and were flying a port orbit about
the 140 mile fix of El Centro TACAN. LT (b) (6) had earlier moved the rendezvous
point from 30 to 140 miles.

Through radio conversations with LT (b) (6) I fixed my position as below
and at the flight's 5 o'clock position. The flight saw me first. I located
them high at my 3 o'clock. I asked LT (b) (6) his air speed which he told
me was 300 knots. My speed at this time was 260 knots. I accelerated to
300 knots as the flight passed above and ahead of me then continued to try
to rendezvous from an astern position. The rate of closure seemed quite
slow so I accelerated to 320 knots and continued to close on the flight.

LT (b) (6) then called that he was coming back to 75% of power and commencing
a descent to return to Miramar. The flight at this time was in a slightly
descending port turn. As they passed the sun I moved to the left side to
improve my vision. As I continued to close I slowed to 310 knots. I passed
to the right side again because of the sun and vision. I was at this time
500 to 600 feet behind and below. As the port turn continued I moved to the
left side again for the same reason, to keep the sun out of my eyes. My visor
was down the entire time. I was at this time slowly closing at 300 knots and
slightly behind and below the flight which was in a V formation. I again passed
to the right side because of vision, this time directly behind the flight.

Enclosure (2)

My sideward movement was quite rapid as I moved approximately 200 feet to the right of the nearest aircraft. At this time I was 100 - 130 feet aft. I rolled approximately 60° bank to stop the sideward movement and to move back in position. I had all three aircraft in sight at this time. My speed was 300 knots. I felt the aircraft continue to roll past the angle of bank that I wanted and the next thing I realized I was inverted. I lost sight of all aircraft at this time. I tried to pull the throttle to idle, drop the speed brakes and pull nose down simultaneously, as I had lost sight of the flight.

I felt what appeared to be slip stream and the nose of my aircraft pitched violently down. I started spinning nearly straight down. I started spin recovery and then heard LT (b) (6) say "Get out of it." I reached for the face curtain and as I pulled it the canopy blew as the handle passed over my eyes. My arms were forced backward into the slip stream. I tried to pull the curtain further but could not. I locked my elbows together in front of my helmet and lunged forward with my head, arms and chest. The seat ejected.

The ejection was much smoother than I had expected. I felt the seat separate and I was tumbling through the air. I spread my arms and legs to stop this and waited for the chute to deploy. Its opening was quite abrupt.

After the chute deployed I saw another chute open to the West approximately a mile from me. I looked for the aircraft and saw both on the ground burning.

The drogue chute weight was tangled on one shroud line and passing to and fro near my head. It hit me several times so I finally cut it loose and dropped it. I had oxygen from the bailout bottle until I released my mask.

I dropped the survival pack 100 - 150 feet in the air. I noticed several cars and people gathering below me.

I landed quite smoothly, released from the chute and tried to signal LT (b) (6) who was circling overhead. Several civilians were at the wreckage of NJ-408. After being assured by a deputy sheriff that the other pilot was uninjured I remained near the wreckage of NJ-408 to await LTJG (b) (6).

We were there together until 1815 at which time we learned a SAR aircraft had landed at Borrego Springs County Airport. LTJG (b) (6) went to the airport to check with the pilots as to whether we should leave the scene. I was advised by a deputy sheriff that I was to go to the aircraft and return to Miramar.

I was driven to the airport and returned to Miramar.

I had no knowledge that I had collided with NJ-408 until I talked with LTJG (b) (6).

I feel this accident would not have happened if the flight had taken a path away from the sun. I cannot honestly say this was the primary cause of the collision. Vision was bad for me even with my visor down. This required me to change my flight path several times and delayed the rendezvous.

27

Before the collision, the sun was not in my eyes. I was concentrating solely on the other three aircraft to the point of a sensation similar to target fixation. I am sure had I broken my scan once I was in close, the collision would not have occurred. I also feel this is the reason I did not notice my aircraft's altitude until it was inverted. I cannot honestly offer any other cause for this other than that I over controlled the aircraft as I banked to the left not realizing it because of the concentrated effort to maintain sight of the other aircraft. I am positive had I constantly shifted my gaze to other points, perhaps the ground, rather than staring at the other aircraft, I could have prevented this accident.

I was designated a Naval Aviator 4 October 1961. My total flight time is 400 hours; total FSU hours - 11.

(b) (6)

1/LT

USMC

28

STATEMENT OF THE PILOT LTJG (b) (6) USNR, (b) (6) 1315 CONCERNING
VF-124 AAR 2-62 FSU-1/FSU-2 BUNO 145396-146975 OCCURRING 27 FEBRUARY 1962

This hop was a routine Form-1 and 2 syllabus flight, and each item was being covered on the brief card up to the time of the accident.

The 4 members of the flight were commencing a TACAN rendezvous OBO radial, 30MI El Centro TACAN. The flight leader and the #2 man (LTJG (b) (6)) joined up without incident. #3 and #4 men were not joined, and the flight leader re-instructed #3 and #4 men to proceed to 290 radial, 40MI El Centro TACAN, and rendezvous there. Flight leader and #2 man established a port orbit at the designated fix, and shortly thereafter, #3 man joined the #1 and #2 men. #4 man was then sighted approximately 2000 feet below, proceeding West. The flight leader instructed him by radio to rendezvous. #4 man completed his rendezvous. The #4 man (1/LT (b) (6)) switched sides, first from port to starboard to keep the sun out of his vision, and about this time, flight leader called for a 75% idle descent. We were in a port turn, when once again, #4 man crossed under from port to starboard. I was flying normal parade in the port turn on the leader, when I noticed #4 going through some unusual gyrations ahead and outside of the turn to port. He (#4) then disappeared from my field of vision, dropping aft and next recollection I have is that of being struck on my underside. I did not see the aircraft hit me.

The sensations I had immediately after impact was that of the aircraft going nose low, severely yawing and dropping with no apparent lift. I worked my stick around, and had no response at all. The aircraft never did go inverted while I was still in it.

Immediately after trying my controls, I ast myself up in erect ejection posture, pulled the face curtain, and ejected. The ejection sequences performed normally, and as advertised. I dropped my seat pack approximately 100 feet from the deck, and I then landed without incident. I vaguely recollect seeing my aircraft shortly after ejection. It looked as if it may have had no wing.

Upon landing, I unstrapped, packed up my gear, and in about 15-20 minutes, local people picked me up and I requested to be taken to the scene of the wreckage. My aircraft apparently landed in a flat attitude, for the fuselage, including the tail section was all intact. The wing was reported to be about 3 miles Southeast of the fuselage wreckage. The accident occurred at approximately 1700, and at approximately 1830, we were flown back to NAS Miramar via Coast Guard UP.

I was designated a Naval Aviator 27 October 1961. I have 350 total flight hours and 310 total jet hours. I have 10 hours in the FSU, with no night time.

I see no possible prevention of this accident from my position (#2 man flying on leader in port turn).

(b) (6)

LTJG

USNR

Enclosure (3)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 70, OPNAVINST 3750.6D

STATEMENT OF THE FLIGHT LEADER LT (b) (6) USN, (b) (6) /1310 CONCERNING
VF-124 AAR 2-62 F8U-1/F8U-2 BUNO 145396-146975 OCCURRING 27 FEBRUARY 1962

The flight consisting of 1/LT (b) (6), 1/LT (b) (6) and LTJG (b) (6) was briefed in the VF-124 Ready Room at 1410 on 27 February 1962. The flight was to be Formation 2 for (b) (6) and (b) (6) and Formation 1 for LTJG (b) (6). The briefing card was followed and in addition some time was spent discussing the standard tacan rendezvous and the desirability during running rendezvous of maintaining lateral separation until reaching abeam so that the closure rate would be positively under control. The students asked a few questions and sounded eager and prepared for the flight. I altered the flight line-up as published on the schedule in order that (b) (6) on his Form 1 would be #2 in the flight where I could keep him under close observation; (b) (6) #3 and (b) (6) #4. The flight call was "Black Flight". The briefing was completed at approximately 1440.

Aircraft were manned at approximately 1500 and we taxied for take off at 1515, Black 4 was delayed slightly while a low tire was inflated. Individual take offs were made commencing at 1523. The flight joined up promptly and as we departed the field and climbed out #3 and #4 were a bit rougher than average. I exercised the flight by signalling wingman and section cross unders all of which were executed satisfactorily. We practiced some "Finger Four" parade formation and some "Instrument parade formation and the flight performed satisfactorily. I had to prompt (b) (6) on one occasion to step up slightly into the proper parade position and also asked the same of (b) (6) during the instrument parade work. At 25,000 feet we practiced three break ups and rendezvous. The latter were fair with a few discrepancies; (b) (6) was allowing his rendezvous to go to a very low angle off too early where as (b) (6) and (b) (6) were acute and had to go to the outside wing to the high closure rate. They did call "going to the outside", and kept each other informed as to their relative positions. With the flight joined again we practiced some tactical wing as briefed. (b) (6) flew my wing and (b) (6) flew (b) (6) approximately a mile behind my section. After several turns during which time we headed generally toward Yuma I advised #3 and #4 to swap positions. I heard them change the lead and then made several more turns still going toward Yuma. I then requested the flight to join up in their present relative positions ie 1,2,4, and 3 and advised we would remain that way until joining up after the touch and go's at Yuma. I checked with Yuma tower for the Duty Runway and advised them we were coming. The flight joined and we descended to initial for Runway 3 at Yuma. As I levelled my wings inbound to initial I advised and signalled the flight to go to left echelon by crossing the section to the port side where Black 2 was already flying. I also advised the flight to change to "Button 3". We were cleared into the break (right hand break and traffic) and I noted that (b) (6) (#2) was flying a poor wing but finally closed up prior to being cleared to break. We executed two touch and go landings each and departed to join up. I advised the flight to utilize the Yuma 280 radial recalling that El Centro tacan was reported inoperative. (b) (6) (#2) joined promptly and I reported my distance from Yuma on the 280 radial to facilitate #4 and #3's rendezvous. Checking I found El Centro tacan operating and advised #4 and #3 to now utilize it. Upon reaching El Centro #4 and #3 had still not joined and I advised them I would

Enclosure (4)

establish a port orbit. After approximately 180° of turn #3 reported having #4 in sight but shortly thereafter reported losing him in the sun. I briefly caught sight of an aircraft over El Centro as I was through 270° of turn but also lost him in the sun. I believed we would be more successful utilizing the standard tacan rendezvous as briefed so transmitted that the flight would now rendezvous on the El Centro 290° radial at 30 miles. This would be taking us in the general direction of Ramona, the Miramar initial. Black #2 (b) (6) flying a good tight wing, and I passed south of El Centro and then turned to intercept the 290 radial at 28,000'. My transfer fuel gauge showed below zero so I thought I would purge the wing and perhaps Black #4 and #3 would see what ever fuel dumped. Some fuel did dump and Black 4 reported, "have you in sight". Black 4 reported joining and also "Bingo", (1900#). Noting that we were in close proximity to restricted area R-2510 and almost at 30 miles, I advised Black 3 (b) (6) that we would continue to 40 miles. I called distance at approximately 36 miles and Black 3 replied he was at 12 miles. At 40 miles on the El Centro 290 radial I announced "point one" and commenced a 30° banked turn at 29,500' after approximately 80° of turn Black 4 (b) (6) joined in echelon on the starboard wing. I asked Black 3 his distance and he replied, twenty odd miles. As we passed point three I again asked distance and he replied 32 miles. We were also at 32 miles and (b) (6) announced "Tally Ho" at 9 O'clock down. I then saw (b) (6) about one mile distant, down approximately 1500 feet in my 1030-11 O'clock to 4 O'clock up and he replied "roger have you". I continued my turn to 290 and (b) (6) passed under my nose still down about 1500'. As I saw him go to my 1:30 to 2 O'clock posit I advised him to "come back port" so that he would not go too far behind. He acknowledged and I observed him start to close now at approximately my 4 O'clock low 1/2 to 3/4 of a mile. I then devoted my attention forward and asked Black 4 his fuel state, he replied 1500#. I asked, if anyone was lower, and Black 3 replied 1400#. I announced I was reducing power to 75%, starting a gentle descent and for the flight to loosen up until we approached initial and then to tighten it up. Black 3 (still joining) requested my airspeed, I replied 270 increasing to 300. The flight was now in a shallow port turn passing approximately 27,000 feet, Black 4 had crossed and was loose (15-20') on my port wing and Black 2 was at the same distance on my starboard wing. I looked out to starboard to see if Black 3 had joined. I saw an aircraft inverted, level with me and abeam, its fuselage no more than 20-30' away. The plane was slightly nose down and appeared to be rolling right and over taking as though just having completed 1/2 of a tight barrel roll. The front third was all I saw and at the time there appeared to be some vortices or vapor at the side of its fuselage. I assumed it was Black 3 because I could not imagine how my right wingman (Black 2) could have maneuvered to that position without hitting me. Fearing a collision I immediately increased my left bank and raised the nose hoping my left wingman could follow me safely as I did so.

After a couple of seconds I turned back starboard and saw an F8U descending and doing what looked like a lazy falling leaf. As the plane continued to fall I saw definitely that the wing was completely missing and fluid was streaming from the wing well. Suspecting how uncontrollable and rapidly the fuselage alone would likely descend I called "GET OUT OF IT!", "GET OUT OF IT NOW!". I wondered if his radio would still be operative and if he would hear me and

Enclosure (4)

got what I thought was my answer as I observed the canopy leave followed by the seat. I saw the pilot drogue and main stabilizer drogue deploy and then realized that I would not see the main parachute until he was at 10,000'. I then looked around for other aircraft and seeing none, switched to Guard and transmitted a MAYDAY call. "Politician" and "El Centro" answered, plus others. I then called El Centro by name and transmitted my approximate position from El Centro (my tacan had unlocked). Politician requested my bearing and distance from Yuma and I told them to standby. I returned to our tactical frequency and asked for any Black flight to check in - Black 4 answered. I asked what he had seen and he reported only that which I too had seen. I asked his state which was 1400# and told him to return to Miramar call the squadron base radio and tell them what had happened. Shortly thereafter we both observed the smoke and flame of a crash NNE of Borrego. I switched back to Guard again called Politician and reported my position from Yuma as 282° radial 95 miles, my tacan was then locked on Yuma. A moment later I selected Emergency IFF and was advised by Politician and San Diego Approach to squawk 3-77 and 1-00 which I did. San Diego also requested that I call them. I did not recognize the small town and airport below but knew that having a positive tacan position would afford search and rescue an accurate location. Soon two chutes became visible and the noise of the PRT-3 beacons became extremely evident to the extent that further transmissions on Guard channel were rendered inaudible. The chutes were approximately 1 mile apart and as they descended into the shadow of the nearby mountain I switched to the ADF position of the ARA-25. The #1 needle only searched back and forth as I suspected Politician and El Centro were still calling and the combination of signals could not be resolved.

I tried calling Politician on Stargazer frequency but got no reply. I then called San Diego Approach Control who advised they also had my position fixed. I then descended and attempted to observe the parachute landings. The PRT-3 beacons stopped as the chutes landed and I descended to determine the pilots' location and condition. I initially saw one chute adjacent a sizable road and observed cars stopping and turning around. As I got closer, the pilot had apparently gathered up the chute for it disappeared. I circled again and saw a pilot in the center of a rather open desert area, there were two station wagon vehicles approaching him and he waved his arms as I passed. Still not certain that I had seen both pilots I orbited until I saw a group of cars at the road side and the other pilot waving also.

During these latter moments I observed an additional plume of smoke marking the second crash. I climbed and orbited the area sketching the location of the aircraft parts on my knee board and noted that none had apparently struck any buildings or property of consequence. There were groups of people around the burning portions of the aircraft, one with a wing and one without. No one was in vicinity of the severed wing which did not catch fire. -I heard and aircraft talking to El Centro, his call was Overpass 777. He relayed to El Centro that the pilots were OK and being picked up by civilians. I advised Politician that the pilots were being picked up and after one last orbit observed both pilots on the ground with civilians and acknowledged their waves by jassing the engine. I departed for Miramar calling San Diego Approach and advised them of the rescue progress. They reported a

Coast Guard UP was enroute and I talked briefly to him on the same frequency. I observed the UP and assured myself he was headed for Borrego. I looked up Borrego in the enroute supplement and saw that it had 5200' of asphalt runway. The UP indicated he would land there and Approach Control reported the Borrego Sheriff was taking the pilots to the airport. I switched to Miramar tower, returned and landed.

(b) (6)

LT

USN

Enclosure (4)

STATEMENT OF 1/LT (b) (6), USMC, (b) (6) 7398 CONCERNING VF-124
AAR 2-62 F8U-1/F8U-2 BUNO 145396-146975 OCCURRING 27 FEBRUARY 1962

The flight started in a very normal fashion with a brief by LT (b) (6). The other pilots in the flight were 1/LT (b) (6) and LTJG (b) (6). (b) (6) and myself were on a formation two (2) hop and (b) (6) was on a formation one (1) hop. LT (b) (6) gave us a complete briefing including all the emergency, lost communication, and Yuma airport procedures.

From take-off until the time of the accident the hop proceeded exactly as briefed. This included parade, instrument parade and finger four formations. We practiced single and section cross-unders, tactical wing position, and break-ups and rendezvous. We then proceeded to Yuma for two touch and go landings.

After two landings each we departed the pattern at Yuma climbing out to flight level 300 on the 080°R of Yuma TACAN. When I was at about 10M LT (b) (6) called for us to switch to the El Centro TACAN and climb out on the 290° radial for a rendezvous at 30 miles. I tuned in El Centro and continued so as to intercept the 290° radial out of El Centro. By this time (b) (6), the number two man, had already joined on number one. When I reported to the leader that I was 10 miles behind him he dumped his wing tanks in an effort to make himself visible to me. At this time I sighted the leader and his wingman directly in front of, and level with, me at a distance of about 9 or 10 miles. I informed the leader (LT (b) (6)) of this and he "rogered". Shortly after this he called and told us to rendezvous at 40 nautical miles instead of 30 nautical miles on the 290° radial. At 40 nautical miles the leader started a port turn for a tacan rendezvous (we had been briefed for this type of rendezvous prior to the hop). By the time the leader and number two man were at the number two position, I was joined on the number two man's wing. (b) (6), by this time, had called and said he was about 20 miles out on the 290° radial. We continued in a port orbit until (b) (6) called and said he was 32 miles out on the 290° radial. At this time we were also 32 miles out having just passed the number 4 position of the tacan rendezvous. Shortly after this I called a "tally ho" on (b) (6) who was crossing from our 5 O'clock position to our 11 O'clock at an altitude about 1000' below us. LT (b) (6) then picked up (b) (6) and gave him our bearing on his aircraft. (b) (6) called "tally ho" and asked what our airspeed was at that time. LT (b) (6) told him it was 270 knots. (b) (6) then started a turn to the right, still below us. I then lost sight of him passing beneath the flight, from left to right.

At this point LT (b) (6) called the flight for a power reduction to 75% and let down to the field. This was to reduce our fuel consumption to a minimum since I had shortly before called a fuel state of 1500#. LT (b) (6) then called and told us to maintain loose positions until just prior to entry to the field.

The sun at this time was almost in a direct line between the leader's aircraft and mine so I elected to cross under to the port side of his aircraft. I did not have visual contact with (b) (6) at this time, nor had I seen him since he crossed under us some time before.

Enclosure (5)

I initiated a section cross under with my right arm thinking that he might be further aft than I had looked. At this point I eased the power back making a normal cross under, at a normal rate of speed. I had just established myself on the left wing of the lead aircraft when I observed what appeared to be the number four aircraft (b) (6) rolling into an inverted position under the number two man (b) (6).

I think LT (b) (6) observed this at the same time I did, as he rolled to the left and pulled away from the number two and four aircraft. When I saw his wing drop I rolled about 70° or 80° and pulled out to the left and up pretty hard. I rolled over on top so I could locate the other aircraft in the flight. LT (b) (6) was at about my 2 O'clock and another aircraft was at about my 4 O'clock pointed about 70° nose down with no wing. LT (b) (6) called "get out", "get out now". Almost immediately the pilot of that aircraft ejected. The canopy left the aircraft, the seat fired, and immediately the drogue chute deployed. The seat and drogue chute rapidly went out of sight.

During this time I was following LT (b) (6) in a tail chase. I still had not fully realized what had happened. I never did see the third aircraft which worried me because I was sure he was in the same general airspace we were in, yet was unable to locate him.

LT (b) (6) then called and asked if anyone in the flight could read him. I answered up and told him I was following him (on his tail). No one else answered so I could only assume the worst.

LT (b) (6) then asked what my fuel state was. I told him 1400#. He then directed me to proceed home and land, and to give base radio a call and tell them what had happened. He was talking to O.C.I. getting a fix on our location prior to this and I assume wanted to return immediately (to guard channel).

I then left the scene and began a track to put me at Ramona for a normal field entry, trying to contact base radio. I finally made contact with base and informed them what had happened and that LT (b) (6) was still orbiting the scene.

Shortly after this I made a normal field entry and landing.

(b) (6)

1/LT USMCR

STATEMENT OF MAINTENANCE OFFICER REGARDING ACCIDENT OCCURRING 27 FEBRUARY 1962
INVOLVING FSU-1 BUNO 145396

1. FSU-1 BUNO 145396 was accepted from Fighter Squadron ONE FOUR TWO on 27 November 1961. It received a calendar intermediate inspection on 5 January 1962. Subsequent to this inspection it had flown 73.8 hours and a total of 943.3 hours since acceptance by the Navy.
2. All pertinent instructions and directives had been complied with as indicated by maintenance records and aircraft logs.
3. The engine, a J-57-P4A, serial number F608170 had 204.3 hours since overhaul and a total of 650.8 hours since new. There were no pertinent uninstalled bulletins.
4. Maintenance records indicate this aircraft was properly serviced and pre-flighted.
5. A review of the past ten OPNAV forms 3760 (Rev 5-61) revealed no outstanding discrepancies, nor any which could have contributed materially to this accident.

(b) (6)

LCDR

USN

Enclosure (21)

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 70, OPNAVINST 3750.6D

RESUME OF PILOT'S FLIGHT EXPERIENCE

(b) (6) 1/LT, (b) (6) /7398, USMC

<u>Training Command</u>	<u>A/C Type</u>	<u>Hours</u>	<u>Carrier Landings</u>
Basic and Advanced	T-34	46.2	0
	T-28	136.6	8
	F9F-8T	85.1	0
	F9F-8B	52.3	4
	F11F-1	<u>25.8</u>	<u>0</u>
TOTAL		346.0	12
Operational			
HMS-33 MCAS El Toro	F9F-8B	9.5	
	F9F-8T	24.7	
	TV-2	6.4	
VF-124 (RAG)	F8U-1, -2	<u>8.5</u>	
Total Operational		49.1	
Total All Types		395.1	
Total Jet Time		225.0	

Designated Naval Aviator 4 October 1961

RESUME OF PILOT'S FLIGHT EXPERIENCE

(b) (6)

LTJG, (b) (6) 1315, USN

Training Command	A/C Type	Hours	Carrier Landings
Basic and Advanced	T-34	37.8	0
	T2J1	120.8	6
	F9F-8T	84.2	0
	F9F-8B	49.0	6
	F11F-1	<u>24.9</u>	<u>0</u>
	TOTAL	316.7	12
Operational			
VA-126 IFTD	F9F-8T	27.1	0
VF-124 (RAG)	F8U-1, -2	<u>9.5</u>	0
Total Operational		36.6	
Total All Types		353.3	
Total Jet Time		315.0	

Designated Naval Aviator October, 1961

ORIGINAL

ADDENDUM TO PAGE 1, ITEM 30 OF VF-124 MOR 3-62

On February 27, 1962 at approximately 1525 uniform time LTJG (b) (6) and 1/LT (b) (6) took off from NAS Miramar as number 2 and 3 men of a scheduled four plane formation training flight. It was the first formation hop for LTJG (b) (6) and the second formation hop for 1/LT (b) (6). Both men had sufficient nutrition and adequate rest in the 24 hours preceding the accident. The flight was thoroughly briefed.

The flight progressed in a normal manner through "finger four", instrument parade, break up and rendezvous, and tactical wing maneuvers. At this point each pilot shot two touch and go landings at MCAAS Yuma, Arizona. LT (b) (6) the flight leader then directed the flight to make a running rendezvous enroute to Miramar via El Centro and LTJG (b) (6) joined on the starboard wing in parade. LT (b) (6) advised 1/LT (b) (6) that the rendezvous point would be on the 290° radial of El Centro at 30 miles. Due to the proximity of a restricted area the rendezvous point was changed to 40 miles and at that point a standard port orbit was set up and after 80° of turn the #4 man, 1/LT (b) (6) joined the flight. After approximately 180° of turn the #4 man sighted 1/LT (b) (6) and he responded with "Roger, have you". 1/LT (b) (6) passed under the formation to the inside of the turn and noted immediate difficulty with keeping the flight in sight due to the setting sun. He, therefore, began maneuvering back and forth from port to starboard behind the formation to avoid the sun's glare and close the formation from astern. The last time he moved across from port to starboard he began to slide out and behind the formation. In an attempt to recover he went into a 60° bank to port, but inadvertently continued the roll to an inverted position at 300 knots. 1/LT (b) (6) lost sight of all three aircraft at this time. He attempted recovery by pulling the throttle to idle, dropping the speed brakes and pulling the nose down. During this inverted maneuver 1/LT (b) (6) airplane collided with LTJG (b) (6) s airplane. The forward portion of (b) (6) fuselage struck the starboard tip of (b) (6) wing (Photo #1) then (b) (6) starboard wing tip dug into the vertical fin of (b) (6) aircraft and scraped along the vertical fin (Photo #2) before striking the starboard wing of (b) (6) airplane. During this sequence of events, the entire wing of (b) (6) aircraft was separated from the fuselage and the starboard wing of (b) (6) aircraft was torn off. (The concentration of damage on the starboard side of both aircraft establishes the fact that 1/LT (b) (6) was inverted at the moment of collision)

After the collision LTJG (b) (6) felt his aircraft pitch nose down and noting no response from the controls he elected to eject. At the same time 1/LT (b) (6) felt his aircraft begin a spinning motion and he attempted anti-spin control procedures when he heard the flight leader transmit "Get out of it! Get out of it now!" 1/LT (b) (6) experienced some difficulty in pulling the face curtain all the way and finally lunged forward in the seat with the total force of the upper half of his body.

The ejections and descents proceeded normally and both pilots landed in the desert on the outskirts of Borrego Springs, California. They were picked up by civilians and taken to Borrego Springs County Airport and then flown to NAS Miramar by Coast Guard UP. Immediate examinations at the NAS Dispensary Miramar were negative.

SECTION A - IDENTIFICATION

1. NAME (Name and mailing address of activity) VF-124, U.S.N.A.S. MIRAMAR 45, CALIFORNIA										2. BOX NUMBER 3-62	
3. SIGNATURE OF Medical Officer (b) (6)										4. DATE 14 Mar 62	
5. TYPE OF MISAP <input checked="" type="checkbox"/> ACCIDENT <input type="checkbox"/> GROUND ACCIDENT <input type="checkbox"/> INCIDENT										6. TIME AND ZONE 1704 U	
7. DATE 27 Feb 62										8. TIME OF DAY 16 min. N. Long. 116d.	
9. MODEL A/C F8U-1										10. BURO 145396	
11. NO. OF OCCUPANTS 1										12. TYPE ACCT. A1/08	
13. DAMAGE CODE A										14. UNIT OPERATING A/C VF-124	
15. INDIVIDUALS INVOLVED - USE ADDITIONAL SHEETS IF REQUIRED. NAME (Last, first and middle initials)										16. UNIT TO WHICH ATTACHED	
17. NAME, DATE										18. FILE/SERV. NO. DESIGNATOR	
19. BILLET										20. BRANCH OF SERVICE	
21. INJURY CODE										22. DISPO SITION	
a. (b) (6)										VF-124	
b. (b) (6)										1stLT	
c. (b) (6)										7398 Pilot	
d. (b) (6)										USMC	
e. (b) (6)										E	
f. (b) (6)										E	
23. CLARIFICATION OF ITEMS 15-22 WHEN NECESSARY											
24. MODEL - OTHER A/C IF INVOLVED F8U-2										25. BURO 146975	
26. NO. OF OCCUPANTS 1										27. UNIT OPERATING A/C VF-124	
28. DAMAGE CODE A										29. REPORT NO 2-62	

30. DETAILED NARRATIVE ACCOUNT OF ACCIDENT (Use additional 8 X 10 1/2 plain sheets if required)

See Attached Addendum

200195

SECTION B - MEDICAL OFFICER'S QUESTIONNAIRE

YES	NO	DID THE FLIGHT SURGEON:	(If "NO" state reason in space below.)
<input checked="" type="checkbox"/>		1. VISIT THE SCENE OF THE MISAP?	
<input checked="" type="checkbox"/>		2. PARTICIPATE FULLY IN THE FIELD INVESTIGATION?	
<input checked="" type="checkbox"/>		3. PARTICIPATE FULLY IN THE DELIBERATIONS OF THE A/C ACCIDENT BOARD?	
GIVE APPROXIMATE NUMBER OF HOURS SPENT BY THE FLIGHT SURGEON:		4. IN FIELD INVESTIGATION 7	5. IN BOARD DELIBERATIONS 6
		6. IN PREPARATION OF THIS REPORT 8	
7. REPORT PREPARATION CHECK LIST			
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
ALL PARTS OF FORM COMPLETED	SURVIVOR NARRATIVES	PHOTOS	CONCLUSIONS AND RECOMMENDATIONS
<input checked="" type="checkbox"/> REQUESTED COPIES FURNISHED			

Item C-18, C-39 and C-40:

Sun glare was a contributing factor to this accident since because of it 1st Lt. (b) (6) began moving laterally back and forth behind the formation from port to starboard to minimize the glare. During the final transition from port to starboard he noted he was slipping outside and behind the formation. At this point faulty attention and poor judgement entered the picture. He was concentrating on the formation's position and closing on them to obtain the proper formation position. To do this he rolled into 60° of left bank and as a result of this overcontrolling he inverted while setting up an excessively fast closure rate. He lost sight of the formation because of the inverted attitude and with the excessive closure rate and overcontrolling collided with LTJG (b) (6) aircraft.

SECTION F - SAFETY, PERSONAL, AND SURVIVAL EQUIPMENT

Prepare a narrative account of damaged or failed items. Identify each item discussed (e.g., F1, F2, etc.)

NAME OF INDIVIDUAL (Last, first, middle)

(b) (6)

MODEL A/C
F80-1

GENERAL DESCRIPTION OF EQUIPMENT	AVAIL- ABLE		SPECIFIC MODEL OR TYPE	UTILIZED		FAILED		DESCRIPTION OF DAMAGE TO EQUIPMENT
	YES	NO		YES	NO	YES	NO	
1. Shoulder harness	X		Martin Baker F-5	X				
2. Lap belt	X		Martin Baker F-5	X				
3. Inertia reel	X		Inertia Reel Assembly	X				
4. G-Suit	X		Z-3 Cutaway	X				
5. Pressure suit-full or partial								
6. Exposure suit								
7. Flight suit (Other than above)	X		Summer Orange	X				
8. Helmet	X		APH-5	X				
9. Goggles/Eyeshield	(1)			(1)		(3)		Paint chips from drague piston cracked visor shield and shattered visor.
10. Shoes	X		Flight (Field)	X				
11. Gloves	X		Leather, light	X				
12. Life vest	X		Mark III		X			
13. Life raft	X		PK-2, H1 Speed Container	X				
14. OTHER:								
15. SIGNAL DEVICE - Flare (Night)	X		Day and Night		X			
16. - Flare (Day)	X		Signal Mod 0		X			
17. - Dye marker	X		Dye Marker		X			
18. - Radio	X (A)		ANPRT 3 Beacon	X		(2)		
19. - Flashlight								
20. - Mirror	X		Survival Signal		X			
21. OTHER:								
22. SURVIVAL GEAR - Knife	X		Survival	X			X	
23. - First aid kit	X		PSK-2		X			
24. - Shelter								
25. - Food								
26. OTHER:								
27. RESCUE - Vehicle	X		Civilian Vehicle	X		(2)		
28. - Sling, Net, Stretcher								
29. OTHER:								

SECTION G - DETAILED EQUIPMENT QUESTIONNAIRE

OXYGEN EQUIPMENT	1. NAME - MODEL OR TYPE A-13-A	2. MODIFICATIONS, IF ANY None (1)
	3. REGULATOR - MODEL OR TYPE Robert SHAW 1881	4. MODIFICATIONS, IF ANY None
	5. PREFLIGHTED BY USER? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	6. IF NO, WHY NOT
	7. LIST DISCREPANCIES NOTED BY PREFLIGHT CHECK	
RELEASE DEVICES	8. OXYGEN SUPPLY: PRIOR TO FLIGHT 520 LITERS (Liquid) P.S.I. (Gas) 325 LITERS (Liquid) P.S.I. (Gas)	
	9. WAS OXYGEN IN USE AT TIME OF ACCIDENT? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
	10. IF YES, WAS SELECTOR SETTING <input checked="" type="checkbox"/> 100% <input type="checkbox"/> NORMAL	
	11. WAS ALL OXYGEN EQUIPMENT NECESSARY FOR THIS FLIGHT AVAILABLE? IF NO, LIST ITEMS AND REASON WHY. <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
	12. WAS OXYGEN MASK REMOVED AT ANY TIME IN FLIGHT? IF YES, GIVE DURATION AND REASON. <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES	
	13. TYPE CHUTE RELEASE DEVICE Martin Baker F-5 (1)	14. TYPE HARNESS RELEASE DEVICE Martin Baker F-5 ()
	15. WHEN WERE RELEASE DEVICES ACTIVATED? during ejection sequence (2)	
	16. WERE DIFFICULTIES ENCOUNTERED WITH RELEASE DEVICES? IF YES, STATE DIFFICULTIES, WHEN ENCOUNTERED AND CAUSE. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
17. WERE DIFFICULTIES ENCOUNTERED AFTER ACTIVATING RELEASE DEVICES? IF YES, STATE DIFFICULTIES, WHEN ENCOUNTERED AND CAUSE. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
18. WAS LIFE LIFT DISPLAYED PRIOR TO ACTIVATING RELEASE DEVICES? IF YES, WHAT DIFFICULTIES DID THIS PRODUCT? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		

(Continued on OPNAV FORM 3750-2C)

SECTION G - DETAILED EQUIPMENT QUESTIONNAIRE (Continued)

NAME OF INDIVIDUAL (Last, first, middle) (b) (6)		MODEL & S/N F8U-1	
RESTRAINT HARNESS	18. INTEGRATED HARNESS SYSTEM, MODEL/TYPE Martin Baker F-5	20. INTEGRATED? <input checked="" type="checkbox"/> FULL <input type="checkbox"/> PARTIAL	21. MODIFICATIONS, IF ANY STATE REASON
	22. DID INTEGRATED HARNESS FIT PROPERLY? IF NO, LIST DISCREPANCIES IN FIT AND GIVE REASONS THEREFOR <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES		
	23. INTEGRATED HARNESS FITTING WAS CONDUCTED BY: <input type="checkbox"/> WEARER <input type="checkbox"/> FLIGHT SURGEON <input checked="" type="checkbox"/> PARACHUTE RIDER <input type="checkbox"/> AVIATION EQUIPMENT OFFICER <input type="checkbox"/> OTHER		
	24. IF SHOULDER HARNESS WAS USED, WAS IT: <input type="checkbox"/> LOCKED <input checked="" type="checkbox"/> UNLOCKED <input type="checkbox"/> TIGHT <input type="checkbox"/> SLACK <input type="checkbox"/> OTHER CONDITION		
HELMET	25. TYPE HELMET APH-5	26. LIST PRESCRIBED MODIFICATIONS Chin Strap, Nape Strap and Hardman Fittings (4)	
	27. OTHER MODIFICATIONS AND REASON FOR THEM		28. DID HELMET FIT PROPERLY? IF NO, GIVE REASON <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
	29. HELMET FITTING WAS CONDUCTED BY: <input type="checkbox"/> WEARER <input type="checkbox"/> FLIGHT SURGEON <input checked="" type="checkbox"/> PARACHUTE RIDER <input type="checkbox"/> AVIATION EQUIPMENT OFFICER <input type="checkbox"/> OTHER		
PARACHUTE	30. TYPE CHUTE Martin Baker F-5	31. LAST PACKING DATE 2-2-62	32. MODEL/TYPE SAILOUT SYSTEM Martin Baker F-5 (2)
	33. DID AUTOMATIC RIGGING FAIL? IF YES, WHY <input checked="" type="checkbox"/> NO		34. WAS RIGGING ACTIVATION <input type="checkbox"/> MANUAL <input checked="" type="checkbox"/> AUTOMATIC
	35. IF MANUALLY ACTIVATED STATE REASON AND ANY DIFFICULTIES ENCOUNTERED		
	37. DID CHUTE OPEN IMMEDIATELY? IF NO, GIVE REASON <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO Barostat set for 10,000 to 13,000 feet (1)		38. ALTITUDE THAT CHUTE OPENED Between 10 and 13,000
	39. EJECTION SEQUENCE WAS: <input type="checkbox"/> SLIGHT <input type="checkbox"/> MODERATE <input checked="" type="checkbox"/> SEVERE upside down with arms and legs extended		41. CONDITION OF CHUTE AFTER OPENING Excellent
	42. CHUTE OSCILLATION PRESENT: <input type="checkbox"/> NONE <input checked="" type="checkbox"/> SLIGHT <input type="checkbox"/> MODERATE <input type="checkbox"/> SEVERE		43. IF OSCILLATION WAS PRESENT, HOW WAS IT STOPPED? Not stopped
	44. WEATHER CONDITIONS DURING DESCENT (List in sequence) Clear with unlimited visibility		45. TOPOGRAPHY OF LANDING SITE desert (2)
46. WAS SAILOUT SYSTEM CONDUCTED? <input checked="" type="checkbox"/> BEFORE EXIT <input type="checkbox"/> AFTER EXIT <input type="checkbox"/> NO <input type="checkbox"/> N.A.		47. WAS SAILOUT SYSTEM USED? IF NOT, WHY <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
48. WHEN WAS IT ACTIVATED? <input type="checkbox"/> BEFORE EXIT <input checked="" type="checkbox"/> AFTER EXIT (3)		49. DID DIFFICULTIES ENCOUNTERED WITH SAILOUT SYSTEM AND THEIR CAUSE, IF ANY	
50. WAS CHUTE MANEUVRED? <input type="checkbox"/> TIGHT <input checked="" type="checkbox"/> BRUS <input type="checkbox"/> LOOSE		51. WAS A SITTING POSITION IN SLING OBTAINED DURING DESCENT? IF NOT, WHY <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES <input type="checkbox"/> NOT ATTEMPTED ()	
52. WAS EJECTION IF PROVIDED (Model/Type) <input type="checkbox"/> NONE MB-F5 (5)		53. WAS PARACHUTE LANYARD CONNECTED TO LIFE VEST & RING? IF NOT, WHY <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES	
54. LIST TYPE OF PARACHUTE TRAINING COMPLETED BY THIS INDIVIDUAL Preflight and ejection seat checkout with sling drill in squadron 1959. Ejection Seat checkout, Feb 1962			
55. IF ATTEMPT WAS MADE TO RELEASE PARACHUTE DURING DESCENT, WAS RELEASE ACTIVATED SUCCESSFULLY? <input type="checkbox"/> YES <input type="checkbox"/> NO			
56. IF G-SUIT, EXPOSURE SUIT, FULL OR PARTIAL PRESSURE SUIT WAS WORN, DID IT FIT PROPERLY? IF NOT, LIST DISCREPANCIES IN FIT AND GIVE REASONS THEREFOR <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
57. WAS G-SUIT EQUIPPED WITH A SPRING-LOADED DISCONNECT ADAPTER? IF NO, GIVE REASON <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
58. LIST ALL ITEMS OF NON-STANDARD CLOTHING OR SURVIVAL EQUIPMENT UTILIZED			
59. WAS ANY ITEM OF EQUIPMENT LOST? IF YES STATE ITEM, WHEN LOST, AND REASON FOR LOSS. <input type="checkbox"/> NO <input type="checkbox"/> YES		60. WAS ANY ITEM OF EQUIPMENT DISCARDED? IF YES, STATE ITEM, WHEN DISCARDED, AND REASON FOR DISCARD. <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES	

SECTION H - EMERGENCY EXIT FROM A/C AND SURVIVAL FACTORS

NAME OF INDIVIDUAL (Last, first, middle)

MODEL A/C

F8U-1

1. EJECTION - Attempted		See Addendum	
2. - Accomplished			
3. - Through canopy			
YES	NO	EJECTION DIFFICULTIES ENCOUNTERED	IF YES, EXPLAIN DIFFICULTIES
X		4. - Prior to	See Addendum
X	2	5. - During	
X		6. - Subsequent to	
7. Give type and model of seat used		MARTIN BAKER F-5	
8. BAIL OUT - Attempted			
		- Accomplished	
9. ALTITUDE AT TIME OF EXIT (feet)		10. ALTITUDE OR MANEUVER OF A/C AT EXIT OR IMPACT	
ABOVE SEA LEVEL 27 M		ABOVE TOPOGRAPHY 26.5 M	
11. COLLISION OF A/C WITH		12. CONTROLLED	
GROUND WATER		YES NO UNKNOWN	
13. POWER		14. WHEELS	
ON OFF		UP DOWN	
15. FLAPS		FULL UP PARTIAL	
16. AIR TEMP.		17. WATER TEMP.	
52 °F		°F	
18. A/C FLOATED		19. TIME IN WATER	
SEC			
20. TIME IN RAFT			
21. EXIT USED		22. IS THIS THE RECOMMENDED EXIT? IF NO STATE REASON FOR CHOICE.	
YES NO			
23. DIFFICULTIES WITH THIS EXIT WERE		24. STATE NATURE OF DIFFICULTY	
IN REACHING IN OPENING IN EXITING			
25. BODY POSITION DURING EXIT			
26. LIST OTHER FACTORS NOT INDICATED ABOVE WHICH AFFECTED EXIT FROM A/C			

SURVIVAL FACTORS: Check factors below which are appropriate for this accident. Prepare a detailed narrative account of the factors checked below and attach to this form. Identify each item discussed by item number (e.g., H30, H31, etc.)

COMMUNICATIONS:		MAINTAINING BODY TEMPERATURE:	
27. Communicated position prior to mishap		28. Items used as shelter	
28. Witnesses at scene		29. Items used as clothing	
29. Electronic signal devices		30. Fire	
30. Visual signal devices		31. OTHER:	
31. Auditory signal devices		ENVIRONMENTAL HAZARDS:	
32. OTHER:		32. Exposure to natural forces	
TRAVEL:		33. Exposure to dangerous animals and plants	
33. LAND		34. Unfriendly native population	
34. WATER		35. OTHER:	
SHELTER:		MORALE:	
35. Life raft		36. Isolation	
36. Parachute		37. Psychological shock	
37. A/C structure		38. Lack of motivation to survive	
38. Natural shelter		39. Boredom	
39. Man-made shelter		40. Rationing, activities, and group coordination	
40. OTHER:		41. OTHER:	
WATER SOURCE:		FOOD SOURCE:	
42. Desalting kit, seawater or solar still		42. Prepared survival rations	
43. Rain, dew, snow, ice, etc.		43. Animals/plants	
44. Processed beverages		44. OTHER:	
45. Canteen, thermos, water breaker, etc.		SURVIVAL TRAINING RECEIVED PRIOR TO MISHAP:	
46. Streams, ponds, wells, etc.		45.	
46. OTHER:			

Item H-3, H-4:

1st.Lt. (b) (6) reported that upon pulling the face curtain, as he reached the level of his forehead, he felt a violent force which he interpreted as wind blast pulling his arms and the face curtain back over his head. He said he thought the canopy had jettisoned early. He did not release the face curtain since he felt he would not be able to reach the auxiliary handle if he did. Therefore, he locked both elbows in front of his face and lunged forward with his entire torso pulling the curtain home. The ejection sequence proceeded normally. Later detailed checks with aviation equipment and survival gear personnel failed to reveal any evidence of premature canopy jettison. The canopy interrupter mechanism was clean. Apparently the canopy did not jettison early, but the force (b) (6) experienced was due to extreme transverse G caused by his airplane minus the starboard wing being in a violent rolling maneuver. This investigator is baffled how the pilot escaped a vertebral injury ejecting in this unorthodox position and maneuver. However, A-P and lateral films of cervical, thoracic and lumbar vertebral were negative for fracture or other osseous deformity.

Item H-5:

Once again the drogue gun piston was a problem during the descent. It was suspended at the level of 1st.Lt. (b) (6) helmet and continually struck his hardhat (Exemplified by several chip marks on the posterior section of the hardhat). It also swung in front of his face several times. He finally alleviated the problem by cutting the piston loose and dropping it. This can also become a problem by becoming entangled in the shroud lines.

Item H-31, H-32 and H-36:

The ejection was seen by several citizens of Borrego Springs, California. The ANPR-3 in 1st.Lt. (b) (6) aircraft was most effective as multiple shorebased facilities and airborne aircraft received the signal. The flight leader stated that the signal was so intensified that he could not transmit or Guard Channel. After descent 1st.Lt. (b) (6) was taken by civilian vehicle to a local airport and returned to NAS Miramar via military aircraft.

SECTION I - PATHOLOGICAL FACTS (Use A to denote ANTE MORTEM; P for POST MORTEM, when known and applicable.)

1. NAME OF INDIVIDUAL (Last, first, middle)

MODEL A/A
FBU-1

2. AGE 29 3. HEIGHT (b) (6) INCHES 4. WEIGHT (b) (6) 5. LOCATION AND DIRECTION FACING AT TIME OF ACCIDENT Forward in Forward Cockpit 6. INJURY CODE E

7. UNCONSCIOUSNESS ☐ SHORT DURATION LITTLE SIGNIFICANCE ☐ OTHER (give time) 8. INTERNAL INJURIES (Non-fatal only)

9. GENERAL CONCUSSION ☐ MILD ☐ SERIOUS ☐ CRITICAL ☐ FATAL 10. FACIAL INJURIES (N. F. S.) 11. INTRA-ORAL INJURIES

12. MIND EYE INJURIES ☐ RIGHT ☐ LEFT 13. MAJOR EYE INJURIES ☐ RIGHT ☐ LEFT

14. TYPE OF FRACTURE	SKULL		VERTEBRAE (Specify No.)					SHOULDER GIRDLE	RIBS	PELVIS	UPPER ARM		LOWER ARM		HAND		UPPER LEG		LOWER LEG		FOOT	
	CRAN.	FACIAL	CERV.	THOR.	LUMBAR	SACRAL	COCCYX				R	L	R	L	R	L	R	L	R	L	R	L
SIMPLE																						
COMPOUND																						
COMMINUTED																						
DIS-LOCATION		JAW																				
												SHOULDER	ELBOW			WRIST		HIP	KNEE		ANKLE	
																HEEL					FOOT	

15. AMPUTATIONS/AVULSIONS (Specify Part) 16. LIST PRE-EXISTING PHYSICAL DEFECTS PRESENT AT TIME OF POST CRASH EXAMINATION

17. SOFT TISSUE INJURIES:	LACERATIONS			CONTUSION/SPRAIN/STRAIN			ABRASIONS			18. <input type="checkbox"/> DROWNED		
	MILD	MODERATE	SEVERE	MILD	MODERATE	SEVERE	MILD	MODERATE	SEVERE			
HEAD (N. F. S.)	VENTRAL									19. <input type="checkbox"/> ASPHYXIATED		
	DORSAL											
NECK										20. SHOULDER <input type="checkbox"/> MILD <input type="checkbox"/> MODERATE <input type="checkbox"/> SEVERE	21. ELBOW <input type="checkbox"/> MILD <input type="checkbox"/> MODERATE <input type="checkbox"/> SEVERE	
THORAX	VENTRAL											
	DORSAL											
ABDOMEN	VENTRAL											
	DORSAL											
EXTREMITIES	UPPER									<input type="checkbox"/> SEVERE	<input type="checkbox"/> SEVERE	
	LOWER											
22. BURNS	DEGREE	1ST	2ND	3RD	1ST	2ND	3RD	1ST	2ND	3RD	23. EXTENT OF CARBONIZATION: <input type="checkbox"/> NONE <input type="checkbox"/> COMPLETE	
FROST BITE	AREA	HEAD (ventral Dorsal)		THORAX (ventral Dorsal)		ARMS		LEGS		ARE TISSUE SPECIMENS OBTAINABLE? <input type="checkbox"/> YES <input type="checkbox"/> NO		

NOTE: Attach a detailed narrative account of injuries, cause, structures causing injury, magnitudes of force, and include whether ANTE- OR POST-MORTEM if determined. It is necessary to give as clear a picture of injury cause and sequence as possible.

24. ADMITTED TO SICK LIST? IF YES, GIVE DIAGNOSIS ☐ YES ☒ NO 25. DIAGNOSIS NO. (NAMES PAGES) 26. ESTIMATED STAY ON SICK LIST DAYS 27. DROWNED? IF YES GIVE REASON ☐ YES ☒ NO 28. ESTIMATED DURATION DAYS 29. PRIMARY CAUSE OF DEATH (Use Basic Diagnostic Nomenclature, NAMES PAGES) 30. SECONDARY CAUSE OF DEATH

31. AUTOPSY PERFORMED? <input type="checkbox"/> YES <input type="checkbox"/> NO		32. PROTOCOL <input type="checkbox"/> ATTACHED <input type="checkbox"/> WILL BE FORWARDED		33. AUTOPSY CONDUCTED BY <input type="checkbox"/> PATHOLOGIST <input type="checkbox"/> FLIGHT SURGEON		IF FLIGHT SURGEON DOES AUTOPSY USE "AUTOPSY GUIDE FOR A/C ACCIDENT FATALITIES", AFIP, 1957.	
34. SPECIMEN	TEST PERFORMED	RESULTS	SPECIMEN	TEST PERFORMED	RESULTS		
BLOOD	1		TISSUE (CNS)				
	2		MUSCLE				
	3		VISCERA				
URINE	RAM	Negative	OTHER:				
G.I. CONTENTS							

35. IF ULTRAVIOLET LIGHT OR OTHER SPECIALIZED INVESTIGATIVE PROCEDURES WERE USED AT THE WISMAP SITE OR AUTOPSY, LIST THEM IN THIS SPACE. FOR EACH ENTRY IN THIS SPACE A NARRATIVE ACCOUNT OF THEIR RESULTS AND INTERPRETATION WILL BE ATTACHED.

SECTION A - IDENTIFICATION

1. ROOM (Name and mailing address of activity) VF-124, USNAS, MIRAMAR 45, CALIFORNIA										2. MOR NUMBER 2-62		
(b) (6) Signature of Medical Officer: DATE: 14 Mar 62					(b) (6) Signature of Appointing Authority: DATE: 14 Mar 62					3. UNIT OPERATING A/C VF-124		
4. TYPE OF MISHAP <input checked="" type="checkbox"/> ACCIDENT <input type="checkbox"/> GROUND ACCIDENT <input type="checkbox"/> INCIDENT			5. TIME AND ZONE 1704 U		6. DATE 27 Feb 62		7. LOCATION Lat 33 deg. 16 min. N. Long 116 deg 22 min. W, Borrego Springs, Calif.					
8. MODEL A/C F8U-2		9. ID. NO. 146975		10. NO. OF OCCUPANTS 1		11. TYPE ACCT. A1/G8		12. DAMAGE CODE A		13. UNIT OPERATING A/C VF-124		
14. INDIVIDUALS INVOLVED - USE ADDITIONAL SHEETS IF REQUIRED. NAME (Last, first and middle initials): IN CONTROL OF A/C (b) (6)			15. UNIT TO WHICH ATTACHED VF-124			16. NAME, RATE LTJG		17. FILE/SERV. NO. DESIGNATOR (b) (6)		18. RILEY /1310 Pilot		
19. BOARD OF SERVICE USN			20. INJURY CODE E			21. DISPO E			22. SITUATION			
23. CLARIFICATION OF ITEMS 15 & 22 WHEN NECESSARY												
24. MODEL OTHER A/C IF INVOLVED F8U-1			25. ID. NO. 145396		26. NO. OF OCCUPANTS 1		27. UNIT OPERATING A/C VF-124		28. DAMAGE CODE A		29. REPORT NO. 3-62	

30. DETAILED NARRATIVE ACCOUNT OF ACCIDENT (Use additional 4 X 10 1/2 plain sheets if required)

See Attached Addendum

SECTION B - MEDICAL OFFICER'S QUESTIONNAIRE

YES	NO	DID THE FLIGHT SURGEON:	(If "NO" state reason in space below.)		
<input checked="" type="checkbox"/>		1. VISIT THE SCENE OF THE MISHAP?			
<input checked="" type="checkbox"/>		2. PARTICIPATE FULLY IN THE FIELD INVESTIGATION?			
<input checked="" type="checkbox"/>		3. PARTICIPATE FULLY IN THE DELIBERATIONS OF THE A/C ACCIDENT BOARD?			
GIVE APPROXIMATE NUMBER OF HOURS SPENT BY THE FLIGHT SURGEON:		4. IN FIELD INVESTIGATION 7	5. IN BOARD DELIBERATIONS 6	6. IN PREPARATION OF THIS REPORT 8	
7. REPORT PREPARATION CHECK LIST					
<input checked="" type="checkbox"/> ALL PARTS OF FORM COMPLETED		<input checked="" type="checkbox"/> SURVIVOR NARRATIVES	<input type="checkbox"/> PHOTOS	<input checked="" type="checkbox"/> CONCLUSIONS AND RECOMMENDATIONS	<input checked="" type="checkbox"/> REQUIRED COPIES FURNISHED

MEDICAL OFFICER'S REPORT OF A/C ACCIDENT, INCIDENT, OR GROUND ACCIDENT - PAGE 1
 OPNAV FORM 3750-8 (REV. 5-58)

See OPNAVINST. 3750.6C for instructions - SPECIAL HANDLING REQUIRED

OPNAV REPORT 3750.7

SECTION A - IDENTIFICATION

1. ROOM (Name and mailing address of activity) VF-124, USNAS, MIRAMAR 45, CALIFORNIA										2. NOS NUMBER 2-62					
3. Signature of Medical Officer (b) (6) LT MC USNR					4. DATE 14 Mar 62		5. Signature of Appointing Authority (b) (6) CDR USA					6. DATE 14 Mar 62			
7. TYPE OF MISHAP <input checked="" type="checkbox"/> ACCIDENT <input type="checkbox"/> GROUND ACCIDENT <input type="checkbox"/> INCIDENT			8. TIME AND ZONE 1704 U		9. DAY 27 Feb 62		10. LOCATION Lat 33 deg. 16 min. N. Long 116 deg 22 min. W, Borrego Springs, Calif.								
11. MODEL A/C F8U-2		12. SUND 146975		13. NO. OF OCCUPANTS 1		14. TYPE ACCT A1/08		15. DAMAGE CODE A		16. UNIT OPERATING A/C VF-124					
17. INDIVIDUALS INVOLVED - USE ADDITIONAL SHEETS IF REQUIRED NAME (Last, first and middle initials) IN CONTROL OF A/C (b) (6)			18. UNIT TO WHICH ATTACHED VF-124			19. RANK LTJG		20. FILE/DEPT. NO. (b) (6) /1310 Pilot		21. BRANCH OF SERVICE USN		22. INJURY CODE E		23. DISPO E	
24. MODEL OTHER A/C IF INVOLVED F8U-1			25. SUND 145396		26. NO. OF OCCUPANTS 1		27. UNIT OPERATING A/C VF-124		28. DAMAGE CODE A		29. REPORT NO. 3-62				
30. DETAILED NARRATIVE ACCOUNT OF ACCIDENT (Use additional 8 X 10 1/2 plain sheets if required)															

See Attached Addendum

SECTION B - MEDICAL OFFICER'S QUESTIONNAIRE

YES	NO	DID THE FLIGHT SURGEON:	(If "NO" state reason in space below.)		
<input checked="" type="checkbox"/>		1. VISIT THE SCENE OF THE MISHAP?			
<input checked="" type="checkbox"/>		2. PARTICIPATE FULLY IN THE FIELD INVESTIGATION?			
<input checked="" type="checkbox"/>		3. PARTICIPATE FULLY IN THE DELIBERATIONS OF THE A/C ACCIDENT BOARD?			
4. IN FIELD INVESTIGATION			5. IN BOARD DELIBERATIONS		6. IN PREPARATION OF THIS REPORT
7			6		8
7. REPORT PREPARATION CHECK LIST					
<input checked="" type="checkbox"/> ALL PARTS OF FORM COMPLETED		<input checked="" type="checkbox"/> SURVIVORS NARRATIVES		<input checked="" type="checkbox"/> REQUIRED COPIES FURNISHED	

ORIGINAL

ADDENDUM TO PAGE 1, ITEM 30 OF VF-124 MOR 3-62

On February 27, 1962 at approximately 1525 uniform time LTJG (b) (6) and 1/LT (b) (6) took off from NAS Miramar as number 2 and 3 men of a scheduled four plane formation training flight. It was the first formation hop for LTJG (b) (6) and the second formation hop for 1/LT (b) (6). Both men had sufficient nutrition and adequate rest in the 24 hours preceeding the accident. The flight was thoroughly briefed.

The flight progressed in a normal manner through "finger four", instrument parade, break up and rendezvous, and tactical wing maneuvers. At this point each pilot shot two touch and go landings at MCAAS Yuma, Arizona. LT (b) (6) the flight leader then directed the flight to make a running rendezvous enroute to Miramar via El Centro and LTJG (b) (6) joined on the starboard wing in parade. LT (b) (6) advised 1/LT (b) (6) that the rendezvous point would be on the 290° radial of El Centro at 30 miles. Due to the proximity of a restricted area the rendezvous point was changed to 40 miles and at that point a standard port orbit was set up and after 80° of turn the #4 man, 1/LT (b) (6) joined the flight. After approximately 180° of turn the #4 man sighted 1/LT (b) (6) and he responded with "Roger, have you". 1/LT (b) (6) passed under the formation to the inside of the turn and noted immediate difficulty with keeping the flight in sight due to the setting sun. He, therefore, began maneuvering back and forth from port to starboard behind the formation to avoid the sun's glare and close the formation from astern. The last time he moved across from port to starboard he began to slide out and behind the formation. In an attempt to recover he went into a 60° bank to port, but inadvertently continued the roll to an inverted position at 300 knots. 1/LT (b) (6) lost sight of all three aircraft at this time. He attempted recovery by pulling the throttle to idle, dropping the speed brakes and pulling the nose down. During this inverted maneuver 1/LT (b) (6)'s airplane collided with LTJG (b) (6)'s airplane. The forward portion of (b) (6)'s fuselage struck the starboard tip of (b) (6) wing (Photo #1) then (b) (6)'s starboard wing tip dug into the vertical fin of (b) (6)'s aircraft and scraped along the vertical fin (Photo #2) before striking the starboard wing of (b) (6)'s airplane. During this sequence of events, the entire wing of (b) (6) aircraft was separated from the fuselage and the starboard wing of (b) (6) aircraft was torn off. (The concentration of damage on the starboard side of both aircraft establishes the fact that 1/LT (b) (6) was inverted at the moment of collision)

After the collision LTJG (b) (6) felt his aircraft pitch nose down and noting no response from the controls he elected to eject. At the same time 1/LT (b) (6) felt his aircraft begin a spinning motion and he attempted anti-spin control procedures when he heard the flight leader transmit "Get out of it! Get out of it now!" 1/LT (b) (6) experienced some difficulty in pulling the face curtain all the way and finally lunged forward in the seat with the total force of the upper half of his body.

The ejections and descents proceeded normally and both pilots landed in the desert on the outskirts of Borrego Springs, California. They were picked up by civilians and taken to Borrego Springs County Airport and then flown to NAS Miramar by Coast Guard UP. Immediate examinations at the NAS Dispensary Miramar were negative.

MEDICAL OFFICER'S REPORT OF A/C ACCIDENT, INCIDENT, OR GROUND ACCIDENT—Page 2

OPNAV FORM 3750-6A (Rev. 5-56)

OPNAV REPORT 3750-7

SECTION C—PHYSIOLOGICAL, HUMAN ENGINEERING, DESIGN, SOCIO-PSYCHOLOGICAL, AND TRAINING FACTORS WHICH CONTRIBUTED IN SOME DEGREE TO THIS A/C ACCIDENT, INCIDENT, OR GROUND ACCIDENT

NAME OF INDIVIDUAL (Last, first, middle)

MODEL A/C

(b) (6)

F8U-2

Check E—Established, S—Suspected, or P—Present for each factor selected. Additional 8X10 1/4 plain sheets will be used for the supporting account of items checked below. Identify each statement with the factor and section identification (e.g., C1, C2, etc.). Attach all sheets pertaining to these factors to this form upon completion.

E	S	P	✓ FACTORS	E	S	P	✓ FACTORS
			PHYSIOLOGICAL:				SOCIO-PSYCHOLOGICAL (Emotional areas from duty sources)
			1. Physically incapacitated in flight				29. Expeditions/Delays
			2. "G" forces				30. Weather
			3. Environmental stress—External				31. Mechanical Problems
			4. " " Internal				32. Social and working relationships
			5. Dysbarism/explosive decompression				33. Personal comfort
			6. Diet				34. Regulations
			7. Fatigue				35. Facilities
			8. Hypoxia				36. Navigation
			9. Related illness				37. Duty assignment
			10. Vertigo/Disorientation/illusions				38. Personality traits
			11. Hyperventilation				NON-STRESS FACTORS:
			12. Drugs				39. Faulty attention
			13. Physical state				40. Poor judgement
			14. OTHER:				41. Forgetfulness
			HUMAN ENGINEERING AND DESIGN:				42. OTHER SOCIO-PSYCHOLOGICAL FACTORS
			15. Personal equipment				
			16. Displays and/or controls				
			17. Work arrangement				
			18. Working environment				
			19. Habit interference				TRAINING FACTORS:
			20. OTHER:				43. Physiological training
			SOCIO-PSYCHOLOGICAL (Emotional areas from non-duty sources)				44. Emergency Procedures training
			21. Pregnancy				45. Survival and rescue training
			22. Illness or death				46. Refresher training
			23. Arguments				47. Transition training
			24. Elated/Depressed state				48. OTHER:
			25. Personal habits—Drinking				
			26. " " Sex				
			27. " " Gambling				
			28. " " Debts				

SECTION D—AIR CREW DATA (fill in where applicable)

1. Flight time past 30 days	12.1	7. Total time in model	9.5
2. Flight time last 24 hours	3.3	8. Number of days grounded last month, give reason	None
3. Number of flights in last 24 hours	2	9. Number of and dates of previous accidents	None
4. Time at controls this flight	1.5		
5. Number of hours duty last 24 hours	None		
6. Total flight time	353.3		

SECTION E—CONTRIBUTING FACTORS AND THEIR ANALYSIS (As contained from Part I, Sec. D and Part VIII of the AER)

NOTE: Fill in this section only on that set of forms prepared for FIRST individual listed in Section A, L.A. 15(a). Attach additional sheets as necessary.

SECTION F - SAFETY, PERSONAL, AND SURVIVAL EQUIPMENT

Prepare a narrative account of damaged or failed items. Identify each item discussed (e.g., F1, F2, etc.)

NAME OF INDIVIDUAL (Last, first, middle)

(b) (6)

MODEL A/E

F8U-2

GENERAL DESCRIPTION OF EQUIPMENT	AVAIL. ASSE. YES NO	SPECIFIC MODEL OR TYPE	UTILIZED		FAILED	
			YES	NO	YES	NO
1. Shoulder harness	X	Martin Baker F-5	X		X	
2. Lap belt	X	Martin Baker F-5	X		X	
3. Inertia reel	X	Inertia Harness Reel Assembly	X		X	
4. O-Suit	X	Z-3 Outaway	X		X	
5. Pressure suit-full or partial						
6. Exposure suit						
7. Flight suit (Other than above)	X	Summer Orange	X		X	
8. Helmet	X	APH-5	X		X	
9. Goggles/Eyeshield						
10. Shoes	X	Flight (Field)	X		X	
11. Gloves	X	Leather light	X		X	
12. Life vest	X	Mark III C		X		
13. Life raft	X	PK-2, Hispeed Container	X			
14. OTHER:						
15. SIGNAL DEVICE - Flare (Night)	X	Day and Night		X		
16. - Flare (Day)	X	Signal Mod O		X		
17. - Dye marker	X	Dye Marker		X		
18. - Radio	X	ANPR13 Beacon		X		
19. - Flashlight	X					
20. - Mirror	X	Survival Signal		X		
21. OTHER:						
22. SURVIVAL SEAR - Knife	X	Survival		X		
23. - First aid kit	X	PSK-2		X		
24. - Shelter						
25. - Food						
26. OTHER:						
27. RESCUE - Vehicle	X	Forest Patrol Truck	X		X	
28. - Sling, Net, Stretcher						
29. OTHER:						

No equipment damaged. Knee board lost during ejection.

SECTION G - DETAILED EQUIPMENT QUESTIONNAIRE

1. BASE - MODEL OR TYPE A-13-A		2. MODIFICATIONS, IF ANY None (1)	
3. REGULATOR - MODEL OR TYPE Firewell 2846 (3)		4. MODIFICATIONS, IF ANY None	
5. PREFLIGHTED BY USER? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		6. IF NO, WHY NOT	
7. LIST DISCREPANCIES NOTED BY PREFLIGHT CHECK			
8. OXYGEN SUPPLY: 5.0 LITERS (Liquid) P.S.I. (Gas) 3.5		9. WAS OXYGEN IN USE AT TIME OF ACCIDENT? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
10. IF YES, WAS SELECTOR SETTING <input checked="" type="checkbox"/> 100% <input type="checkbox"/> NORMAL		11. WAS ALL OXYGEN EQUIPMENT NECESSARY FOR THIS FLIGHT AVAILABLE? IF NO, LIST ITEMS AND REASON WHY. <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
12. WAS OXYGEN MASK REMOVED AT ANY TIME IN FLIGHT? IF YES, GIVE DURATION AND REASON. <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES			
13. TYPE EMERGENCY RELEASE DEVICE Martin Baker F-5 (1)		14. TYPE HARNESS RELEASE DEVICE Martin Baker F-5 (1)	
15. WHEN WERE RELEASE DEVICES ACTIVATED? During ejection sequence (2)			
16. WERE DIFFICULTIES ENCOUNTERED WITH RELEASE DEVICES? IF YES, STATE DIFFICULTIES, WHEN ENCOUNTERED AND CAUSE. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
17. WERE DIFFICULTIES ENCOUNTERED AFTER ACTIVATING RELEASE DEVICES? IF YES, STATE DIFFICULTIES, WHEN ENCOUNTERED AND CAUSE. <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
18. WAS LIFE VEST INFLATED PRIOR TO ACTIVATING RELEASE DEVICES? IF YES, WHAT DIFFICULTIES DID THIS PRESENT? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			

(Continued on OPNAV FORM 3750-8C)

SECTION 6 - DETAILED EQUIPMENT QUESTIONNAIRE (Continued)

(b) (6)

FORM 3750-2

RESTRAINT HARNESS	19. INTEGRATED HARNESS SYSTEM, MODEL/TYPE Martin Baker F-5 (1)		20. INTEGRATED? <input checked="" type="checkbox"/> FULL <input type="checkbox"/> PARTIAL		21. MODIFICATIONS, IF ANY STATE REASON	
	22. DID INTEGRATED HARNESS FIT PROPERLY? IF NO, LIST DISCREPANCIES IN FIT AND GIVE REASONS THEREFOR <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES					
	23. INTEGRATED HARNESS FITTING WAS CONDUCTED BY: <input type="checkbox"/> WEARER <input type="checkbox"/> FLIGHT SURGEON <input checked="" type="checkbox"/> PARACHUTE RIGGER <input type="checkbox"/> AVIATION EQUIPMENT OFFICER <input type="checkbox"/> OTHER					
	24. IF SHOULDER HARNESS WAS USED, WAS IT: <input checked="" type="checkbox"/> LOCKED <input type="checkbox"/> UNLOCKED <input type="checkbox"/> TIGHT <input type="checkbox"/> SLACK <input type="checkbox"/> OTHER CONDITION					
HELMET	25. TYPE HELMET APH-5		26. LIST PRESCRIBED MODIFICATIONS Chin Strap, Nape Strap and Hardman Fittings (4)			
	27. OTHER MODIFICATIONS AND REASON FOR THEM		28. DID HELMET FIT PROPERLY? IF NO, GIVE REASON <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
	29. HELMET FITTING WAS CONDUCTED BY: <input type="checkbox"/> WEARER <input type="checkbox"/> FLIGHT SURGEON <input checked="" type="checkbox"/> PARACHUTE RIGGER <input type="checkbox"/> AVIATION EQUIPMENT OFFICER <input type="checkbox"/> OTHER					
	30. TYPE CHUTE (8) Martin Baker F-5					
PARACHUTE	31. LAST PACKING DATE 19 Feb 62		32. MODEL/TYPE BAILOUT OXYGEN (2) Martin Baker F-5		33. AUTOMATIC RIFCORD, IF INSTALLED (Model and type) <input type="checkbox"/> NONE Martin Baker F-5 (3)	
	34. DID AUTOMATIC RIFCORD FAIL? IF YES, WHY? <input checked="" type="checkbox"/> NO				35. WAS RIFCORD ACTIVATION <input type="checkbox"/> MANUAL <input checked="" type="checkbox"/> AUTOMATIC	
	36. IF MANUALLY ACTIVATED STATE REASON AND ANY DIFFICULTIES ENCOUNTERED					
	37. DID CHUTE OPEN IMMEDIATELY? IF NO, GIVE REASON <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO Barostat set for 10,000 to 13,000 feet (1)				38. ALTITUDE THAT CHUTE OPENED Between 10,000 & 13,000 feet	
	39. OPENING SHOCK WAS: <input type="checkbox"/> SLIGHT <input type="checkbox"/> MODERATE <input checked="" type="checkbox"/> SEVERE		40. BODY ATTITUDE AT OPENING Erect with lateral spin		41. CONDITION OF CHUTE AFTER OPENING excellent	
	42. CHUTE OSCILLATION PRESENT: <input type="checkbox"/> NONE <input checked="" type="checkbox"/> SLIGHT <input type="checkbox"/> MODERATE <input type="checkbox"/> SEVERE		43. IF OSCILLATION WAS PRESENT, HOW WAS IT STOPPED? not stopped			
	44. WEATHER CONDITIONS DURING DESCENT (List in sequence) Clear with unlimited visibility				45. TOPOGRAPHY OF LANDING SITE desert (2)	
	46. WAS BAILOUT OXYGEN CONNECTED? <input checked="" type="checkbox"/> BEFORE EXIT <input type="checkbox"/> AFTER EXIT <input type="checkbox"/> NO <input type="checkbox"/> N.A.		47. WAS BAILOUT OXYGEN USED? IF NOT, WHY <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
	48. WHEN WAS IT ACTIVATED? <input type="checkbox"/> BEFORE EXIT <input checked="" type="checkbox"/> AFTER EXIT (3)		49. GIVE DIFFICULTIES ENCOUNTERED WITH BAILOUT OXYGEN AND THEIR CAUSE, IF ANY			
	50. WAS CHUTE HARNESS <input type="checkbox"/> TIGHT <input checked="" type="checkbox"/> SNUG <input type="checkbox"/> LOOSE		51. WAS A SITTING POSITION IN SLING OBTAINED DURING DESCENT? IF NOT, WHY? <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES <input type="checkbox"/> NOT ATTEMPTED ()			
	52. SEAT CUSHION IF PROVIDED (Model/Type) <input type="checkbox"/> NONE MB-F5 (5)		53. WAS PARACHUTE LANYARD CONNECTED TO LIFE VEST & BUILT? IF NOT, WHY? <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES			
	54. LIST TYPE OF PARACHUTE TRAINING COMPLETED BY THIS INDIVIDUAL <input type="checkbox"/> NONE Preflight, ejection seat and sling drill, Feb 1962					
55. IF ATTEMPT WAS MADE TO RELEASE PARACHUTE DURING DESCENT, WAS RELEASE ACTIVATED SUCCESSFULLY? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO						
56. IF A SUIT, EXPOSURE SUIT, FULL OR PARTIAL PRESSURE SUIT WAS WORN, DID IT FIT PROPERLY? IF NOT, LIST DISCREPANCIES IN FIT AND GIVE REASONS THEREFOR <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO						
57. WAS A SUIT EQUIPPED WITH A SPRING-LOADED DISCONNECT ADAPTER? IF NO, GIVE REASON <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO						
58. LIST ALL ITEMS OF NON-STANDARD CLOTHING OR SURVIVAL EQUIPMENT UTILIZED						
OTHER	59. WAS ANY ITEM OF EQUIPMENT LOST? IF YES STATE ITEM, WHEN LOST, AND REASON FOR LOSS. <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES (3)			60. WAS ANY ITEM OF EQUIPMENT DISCARDED? IF YES, STATE ITEM, WHEN DISCARDED, AND REASON FOR DISCARD. <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES		

SECTION H - EMERGENCY EXIT FROM A/C AND SURVIVAL FACTORS

NAME OF INDIVIDUAL (Last, first, middle)

(b) (6)

MODEL A/C
F8U-2

1. EJECTION - Attempted		REMARKS	
2. - Accomplished			
3. - Through canopy			
YES	NO	EJECTION DIFFICULTIES ENCOUNTERED	IF YES, EXPLAIN DIFFICULTIES
<input checked="" type="checkbox"/>	<input type="checkbox"/>	4. - Prior to	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	5. - During	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	6. - Subsequent to	
7. Give type and model of seat used		Martin Baker F5	
8. BAIL OUT - Attempted			
		- Accomplished	
9. ALTITUDE AT TIME OF EXIT		10. ALTITUDE OR MANEUVER OF A/C AT EXIT OR IMPACT	
ABOVE SEA LEVEL 2700 (A)		60 deg nose down, upright wing missing	
12. COLLISION OF A/C WITH		11. AIRSPEED	
GROUND <input checked="" type="checkbox"/> WATER <input type="checkbox"/>		300 kts	
13. CONTROLLED		14. POWER	
YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/>		ON <input checked="" type="checkbox"/> OFF <input type="checkbox"/>	
15. WHEELS		16. FLAPS	
UP <input checked="" type="checkbox"/> DOWN <input type="checkbox"/>		FULL <input type="checkbox"/> UP <input checked="" type="checkbox"/> PARTIAL <input type="checkbox"/>	
17. CANOPY POSITION AT EXIT OR IMPACT		18. SEA STATE	
OPEN <input type="checkbox"/> CLOSED <input type="checkbox"/> JETTISONED <input checked="" type="checkbox"/>		52'	
19. AIR TEMP.		20. WATER TEMP.	
52°		52°	
21. A/C FLOATED		22. TIME IN WATER	
SEC.			
23. TIME IN RAFT			
BAIL OUT OR COLLISION WITH WATER OR GROUND		24. EXIT USED	
		25. IS THIS THE RECOMMENDED EXIT? IF NO STATE REASON FOR CHOICE.	
		YES <input type="checkbox"/> NO <input type="checkbox"/>	
26. DIFFICULTIES WITH THIS EXIT WERE		27. STATE NATURE OF DIFFICULTY	
IN REACHING <input type="checkbox"/> IN OPENING <input type="checkbox"/> IN EXITING <input type="checkbox"/>			
28. BODY POSITION DURING EXIT			
29. LIST OTHER FACTORS NOT INDICATED ABOVE WHICH AFFECTED EXIT FROM A/C			

SURVIVAL FACTORS: Check factors below which are appropriate for this accident. Prepare a detailed narrative account of the factors checked below and attach to this form. Identify each item discussed by item number (e.g., H30, H31, etc.)

COMMUNICATIONS:		MAINTAINING BODY TEMPERATURE:	
30. Communicated position prior to mishap		30. Items used as shelter	
31. Witnesses at scene		31. Items used as clothing	
32. Electronic signal devices		32. Fire	
33. Visual signal devices		33. OTHER:	
34. Auditory signal devices		ENVIRONMENTAL HAZARDS:	
35. OTHER:		34. Exposure to natural forces	
TRAVEL:		35. Exposure to dangerous animals and plants	
36. LAND		36. Unfriendly native population	
37. WATER		37. OTHER:	
SHELTER:		MORALE:	
38. Life raft		38. Isolation	
39. Parachute		39. Psychological shock	
40. A/C structure		40. Lack of motivation to survive	
41. Natural shelter		41. Boredom	
42. Man-made shelter		42. Rationing, activities, and group coordination	
43. OTHER:		43. OTHER:	
WATER SUPPLIES:		FOOD SOURCE:	
44. Desalting kit, evaporator or solar still		44. Prepared survival rations	
45. Rain, dew, snow, ice, etc.		45. Animals/plants	
46. Processed beverages		46. OTHER:	
47. Canteen, thermos, water breaker, etc.		SURVIVAL TRAINING RECEIVED PRIOR TO MISHAP:	
48. Streams, ponds, wells, etc.		47.	
49. OTHER:			

ADDENDUM to Page #5, Section H of MOR 2-62 of VF-124

Item #H-31 and H-36

The ejected pilots were seen by several citizens of Borrego Springs, California. As a result LTJG (b) (6) was picked up immediately after he descended. He contacted 1stLT (b) (6) and was taken by private vehicle to a nearby civilian airport where he was picked up by a Coast Guard UP and returned to NAS MIRAMAR.

SECTION I - PATHOLOGICAL FACTS (Use A to denote ANTE MORTEM; P for POST MORTEM, when known and applicable.)

1. NAME OF INDIVIDUAL (Last, first, middle) **(b) (6)** MODEL A/C **F8U-2**

2. AGE **24** 3. HEIGHT **(b) (6)** INCHES **(b) (6)** 4. LOCATION AND DIRECTION FACING AT TIME OF ACCIDENT **Forward in forward cockpit** 5. INJURY CODE **E**

6. UNCONSCIOUSNESS ☐ SHORT DURATION ☐ LITTLE SIGNIFICANCE ☐ OTHER ☐ (give time) 7. INTERNAL INJURIES (Pneum-Joint Injury)

8. Cerebral Concussion ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL 9. FACIAL INJURIES (A. P. C.) 10. INTRA-ORAL INJURIES

11. HEAD INJURIES ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL 12. MAJOR EYE INJURIES ☐ RIGHT ☐ LEFT ☐ RIGHT ☐ LEFT

13. TYPE OF FRACTURE ☐ CRAN. ☐ FACIAL ☐ CERV. ☐ HOB. ☐ LUMBAL ☐ SACRAL ☐ COCCYX ☐ SHOULDER ☐ RIBS ☐ PELVIS ☐ UPPER ARM ☐ LOWER ARM ☐ HAND ☐ UPPER LEG ☐ LOWER LEG ☐ FOOT

14. TYPE OF FRACTURE ☐ SIMPLE ☐ COMPOUND ☐ COMMINUTED

15. DISLOCATION ☐ ANKLE ☐ SHOULDER ☐ ELBOW ☐ WRIST ☐ HIP ☐ KNEE ☐ ANGLE ☐ FOOT

16. AMPUTATIONS/STYLINGS (State Parts) 17. LIST PRE-EXISTING PHYSICAL DEFECTS PRESENT AT TIME OF POST CRASH EXAMINATION

18. SOFT TISSUE INJURIES ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL

19. LACERATIONS ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL 20. CONUSION/SPRAIN/STRAIN ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL

21. ABRASIONS ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL 22. BURNED ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL

23. HEAD (A. P. C.) ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL 24. NECK ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL

25. THORAX ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL 26. ABDOMEN ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL

27. EXTREMITIES ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL 28. EXTENT OF CARCINOMATIZATION: ☐ NONE ☐ COMPLETE

29. BURNS ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL 30. FOOT SITE ☐ MILD ☐ MODERATE ☐ SEVERE ☐ CRITICAL ☐ FATAL

31. NOTE: Attach a detailed narrative account of injuries, cause, structures causing injury, magnitudes of force, and include whether ANTE- OR POST-MORTEM if determined. It is necessary to give as clear a picture of injury cause and sequence as possible.

32. IDENTIFIED TO SIDE LEFT? IF YES, GIVE SEQUENCE ☐ YES ☒ NO 33. IDENTIFIED TO SIDE RIGHT? IF YES, GIVE SEQUENCE ☐ YES ☒ NO

34. ESTIMATED STAY ON SIDE LIST ☐ YES ☒ NO 35. ESTIMATED DURATION ☐ YES ☒ NO

36. PRIMARY CAUSE OF DEATH (Use Basic Diagnostic Nomenclature, ICD-9-CM) 37. SECONDARY CAUSE OF DEATH

38. AUTOPSY PERFORMED? ☐ YES ☒ NO 39. AUTOPSY CONDUCTED BY ☐ PATHOLOGIST ☐ FLIGHT SURGEON

40. SPECIMEN ☐ YES ☒ NO 41. TEST PERFORMED ☐ YES ☒ NO 42. RESULTS ☐ YES ☒ NO

43. SPECIMEN ☐ YES ☒ NO 44. TEST PERFORMED ☐ YES ☒ NO 45. RESULTS ☐ YES ☒ NO

46. SPECIMEN ☐ YES ☒ NO 47. TEST PERFORMED ☐ YES ☒ NO 48. RESULTS ☐ YES ☒ NO

49. SPECIMEN ☐ YES ☒ NO 50. TEST PERFORMED ☐ YES ☒ NO 51. RESULTS ☐ YES ☒ NO

52. SPECIMEN ☐ YES ☒ NO 53. TEST PERFORMED ☐ YES ☒ NO 54. RESULTS ☐ YES ☒ NO

55. SPECIMEN ☐ YES ☒ NO 56. TEST PERFORMED ☐ YES ☒ NO 57. RESULTS ☐ YES ☒ NO

58. SPECIMEN ☐ YES ☒ NO 59. TEST PERFORMED ☐ YES ☒ NO 60. RESULTS ☐ YES ☒ NO

61. SPECIMEN ☐ YES ☒ NO 62. TEST PERFORMED ☐ YES ☒ NO 63. RESULTS ☐ YES ☒ NO

64. SPECIMEN ☐ YES ☒ NO 65. TEST PERFORMED ☐ YES ☒ NO 66. RESULTS ☐ YES ☒ NO

67. SPECIMEN ☐ YES ☒ NO 68. TEST PERFORMED ☐ YES ☒ NO 69. RESULTS ☐ YES ☒ NO

CONCLUSIONS AND RECOMMENDATIONS to VF-124 MOR 2-62

LTJG (b) (6) was in positive control of his aircraft at the time of collision and did not contribute to the accident other than passively as an innocent victim of location. He ejected wisely and the entire ejection, descent and recovery occurred without error or malfunction.

CONCLUSIONS AND RECOMMENDATIONS to VF-124 MCR 3-62

CONCLUSIONS:

1. This accident was due to pilot factor. 1st.Lt. (b) (6) fixed his attention on the formation as he began to lose the proper position he had never gained. Due to sole and dedicated intent to join the formation he overcontrolled his aircraft to an inverted position with an excessively rapid closure rate and resultant midair collision. He thereby violated a continually taught principle in formation flying. Relative motion on a formation must be ceased at a safe distance followed by slow and careful movement into position.

2. Sun glare was a contributing factor in that 1st.Lt. (b) (6) radical manipulation was precipitated as a result of attempts to avoid it.

3. 1st.Lt. (b) (6) experience as an FSU pilot was minimal and may have played a small part in his lack of judgement and faulty attention.

4. The drogue gun piston hangs down to the level of the pilot's head on many descents following ejection and constitutes a hazard to the pilot's head and also in that it may become entangled in the shroud lines.

RECOMMENDATIONS:

1. The absolute necessity of slow and deliberate movement in and about formation flights especially with regards to closing.

2. That the ANFET-3 be actuated on ejection vice seat separation to gain extension of transmission time.

3. Consultation with the local Martin-Baker representative reveals no drogue assembly change which will eliminate the drogue piston problem during descent which is feasible.




REEL: 6 - SHOWING FIRE DAMAGE TO THE FUSELAGE OF NJ-433

all



ENCL: 7 - SHOWING FIRE DAMAGE TO THE FUSELAGE OF NJ-408



ENCLOSURE 8 - SHOWING PAINT MARKS ON THE VERTICAL FIN OF MJ-408



FIGURE 9 - REMOVED PAINT MARKS AND COLLISION DAMAGE TO THE DORSAL FIN OF HJ-408



ENCL. 10 - SHOWING COLLISION DAMAGE TO THE VERTICAL FIN OF NJ-408



ENCL. 11 - SHOWING ENTIRE WING OF NJ-406, THE COLLISION DAMAGE TO THE STARBOARD TIP, AND THE GROUND SCAR. WING AS SHOWN, IS INVERTED



INCL: 12 - SHOWING THE PORT VIEW OF HJ-433



INCL: 13 - SHOWING SEVERED STARBOARD WING OF NJ-433 AT ITS GROUND IMPACT POINT

ENCL. 1A - SHOWING PAINT MARKS ON STARBOARD WING TIP OF H4-433





ENCL. 15 - BURNING BROKEN STARBOARD WING PIVOT FITTING OF HJ-408



ENCL. 14 - SHOWING RESULT OF SIDE LOAD FORCES ON WING ACTUATING ROD OF FJ-408



FIGURE 17 - MODELS DISPLAYING INITIAL IMPACT OF FORECAST OF NG-105 WITH EXTENDED WING TIP OF NG-106




ENCL. 14 - SHOWING RESULT OF SIDE LOAD FORCES ON WING ACTUATING ROD OF HJ-408



ENCL 2B - BOMBS IMPACTING IMPACT OF STARBOARD WING OF NJ-433 WITH VERTICAL
FIN OF NJ-408



ENCLOSURE 19 - PHOTOS DEPICTING THE FINAL AND DISABLING IMPACT OF STARBOARD WING OF NJ-433 WITH PORT WING OF NJ-408



ENCL. 20 - TERRAIN MAP OF BORRERO SPRINGS AREA DEPICTING WRECKAGE DISTRIBUTION